WARRENSBURG

SKYHAVEN (RCM)(KRCM) 3 NW UTC-6(-5DT) N38°47.05′ W93°48.17′	KANSAS CITY
798 B NOTAM FILE COU	L—27A
RWY 01-19: H4206X75 (CONC) S-21, D-26 MIRL	IAP
RWY 01: REIL. PAPI(P4L)—GA 3.0° TCH 36 '. Trees.	
RWY 19: REIL. PAPI(P4L)-GA 3.0° TCH 39 '. Rgt tfc.	61
RWY 14-32: H2801X60 (ASPH) S-12.5 MIRL 0.4% up NW	<u>ь</u> т_т_
RWY 14: REIL. Trees. Rgt tfc.	
RWY 32: REIL. Road.	- 30 3 A
SERVICE: S2 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 14 and	0 0
Rwy 32, Rwy 01–19; PAPI Rwy 01 and Rwy 19; MIRL Rwy 01–19	a a
and Rwy 14–32—CTAF.	R G G G G G
AIRPORT REMARKS: Attended Mon–Fri 1300–0100Z‡, Sat 1400–2300Z‡,	× 00
Sun 1400–2200Z‡. High volume student training invof arpt from	420
1300–2330Z‡ Mon–Fri. Calm wind Rwy 01. South 100' of apron	
and exit ramp located 1250' N of Rwy 01 thId has same pavement	50 0°
strength as Rwy 01–19, remainder of apron not full strength. Limited	G 03
sight distance fm Rwy 14 thId area to Rwy 19 thId and from Rwy 19	
thid to Rwy 32 thid area.	
AIRPORT MANAGER: 660-422-1110	
WEATHER DATA SOURCES: AWOS-3PT 119.575 (660) 422-7010.	
COMMUNICATIONS: CTAF/UNICOM 123.0	~
(R) WHITEMAN APP CON 127.45 (Opr 1300–0500Z‡ Mon–Fri;	
1400–2300Z‡ Sat–Sun; clsd hol) other times ctc	
R WHITEMAN DEP CON 125.925 (Opr 1300–0500Z‡ Mon–Fri; 1400–2300Z‡ Sat–Sun; clsd hol) oth	
(C) KANSAS CITY CENTER APP/DEP CON 135.575 (Opr 0500–1300Z‡ Mon–Fri; 2300–1400Z‡ Sat–Sun;	
CLEARANCE DELIVERY PHONE: For CD ctc Whiteman Apch at 660-687-3132. When Whiteman Apch is	clsd, ctc Kansas City
ARTCC at 913-254-8508.	
RADIO AIDS TO NAVIGATION: NOTAM FILE COU.	
	NM to fld. 878/7E.
TACAN AZIMUTH & DME unusable:	
220°-230° byd 35 NM blo 2,000 '	

WARSAW

HARRY S TRUMAN DAM & RESERVOIR SPB (75U) 1 E UTC-6(-5DT) N38°13.00' W93°25.01' KANSAS CITY 706 NOTAM FILE COU

WATERWAY ALL-WAY: 15000X4000 (WATER)

SEAPLANE REMARKS: Unattended. Waterway All Way trees and high ground all quadrants. Waterway ALL WAY ldgs allowed any direction in designated areas only. Seaplane base is located under the Truman C MOA base 500[°] AGL. Contact WHITEMAN APP on freq 127.45. Debris on and in vicinity of lake during floodings. No buoys showing ldg area. Remain 1000[°] (ear of dam or any bridge. Call for ice conditions in winter months. AIRPORT MANAGER: 816-389-3869

COMMUNICATIONS: CTAF 122.9

KANSAS CITY