
FORT ANN**HARRIS** (83K) 2 W UTC-5(-4DT) N43°24.59' W73°31.96'

NEW YORK

261 NOTAM FILE BTW

RWY 04-22: 2200X50 (TURF) 1.7% up SW**RWY 04:** Tree. Rgt tfc.**RWY 22:** Tree.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Unattended. No flying west of rwy over houses. Upslope at thld Rwy 22.**AIRPORT MANAGER:** 518-232-7896**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

FRANCIS S GABRESKI (See WESTHAMPTON BEACH on page 254)

FRANKFORT-HIGHLAND (See UTICA/FRANKFORT on page 250)

FREDERICK DOUGLASS/GREATER ROCHESTER INTL (See ROCHESTER on page 239)

FREEHOLD (115) 1 NW UTC-5(-4DT) N42°21.84' W74°03.90'

NEW YORK

440 NOTAM FILE BTW

RWY 12-30: H2275X22 (ASPH) 0.7% up NW**RWY 12:** Trees.**RWY 30:** Trees.**AIRPORT REMARKS:** Attended Apr-Dec 1400Z†-dusk. Extensive glider activity, especially on weekends. Rwy 12-30 sfc broken and spalling for entire length. Ctc arpt manager for fld conditions Dec 1-Apr 1, 518-966-8503. Rgt tfc for gliders Rwy 12 only. Rwy 12-30 100' by 2640' turf rwy adjacent to paved rwy (south edge) beginning at 735' from Rwy 30 thld.**AIRPORT MANAGER:** 518-253-4859**COMMUNICATIONS:** CTAF 122.85**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

FRIKK N40°46.59' W73°28.95' NOTAM FILE FRG.**NDB (LOMW)** 407 FR 146° 4.2 NM to Republic. 142/14W.