

HUDSON

COLUMBIA CO (1B1) 4 NE UTC-5(-4DT) N42°17.48' W73°42.62'

198 B LRA NOTAM FILE BTV

RWY 03-21: H5350X100 (ASPH-GRVD) S-69, D-111, 2D-358

PCN 29 F/C/X/T MIRL

RWY 03: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.

RWY 21: REIL. PAPI(P4R)—GA 3.52° TCH 41'. Thld dsplcd 160'. Tree.

SERVICE: S3 FUEL 100, 100LL, JET A1+ OX 1, 3 LGT ACTIVATE

REIL Rwy 03 and Rwy 21; MIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Attended 1200-2300Z†. Wildlife on and invof arpt.

Grass cutting eqpt ops adj to all op svc areas, dalgt hrs Apr-Oct. 100LL self-svc avbl 24 hrs. Full svc Jet A avbl aft hrs by prior arrgmnt, call 518-828-9461. Rwy cond not mnt or rptd when arpt unatndd. Rwy 21 dsgrd calm wind rwy.

AIRPORT MANAGER: 518-828-0871

WEATHER DATA SOURCES: AWOS-3 133.525 (518) 828-2577.

COMMUNICATIONS: CTAF/UNICOM 123.05

® **ALBANY APP/DEP CON** 132.825

CLEARANCE DELIVERY PHONE: For CD etc Albany Apch at 518-862-2299.

RADIO AIDS TO NAVIGATION: NOTAM FILE ALB.

ALBANY (L) (L) VORTACW 115.3 ALB Chan 100 N42°44.84'

W73°48.19' 184° 27.7 NM to fld. 273/13W.

VOR unusable:

045°-065° byd 11 NM

066°-069° byd 11 NM blo 10,000'

078°-088° byd 20 NM blo 10,000'

109°-121°

121°-131° byd 30 NM

121°-131° wi 30 NM blo 9,900'

131°-168°

184°-189°

226°-269° byd 29 NM blo 15,000'

312°-315°

333°-343°

TACAN AZIMUTH unusable:

032°-042° byd 15 NM

164°-168°

303°-308° byd 37 NM

308°-333°


DME unusable:

303°-308° byd 37 NM

NEW YORK

H-101, 11C, 12K, L-33B, 34I

IAP



HUDSON VALLEY RGNL (See POUGHKEEPSIE on page 238)

HUGUENOT N41°24.58' W74°35.50' NOTAM FILE ISP.

(H) (H) VOR/DME 116.1 HUO Chan 108 093° 9.1 NM to Randall. 1300/11W.

VOR unusable:

029°-045°

050°-060° byd 10 NM

061°-079°

210°-230° byd 20 NM blo 6,500'

DME unusable:

037°-048° byd 20 NM

215°-225° byd 33 NM

RCO 122.1R 116.1T (NEW YORK RADIO)

NEW YORK

H-101, 12I, L-33A, 34H

HUNTER N42°51.25' W73°56.01' NOTAM FILE SCH.

NDB (MHW) 356 HEU at Schenectady Co. 332/14W.

NEW YORK

L-32G

INDEPENDENT HELIPORT (See NEW WINDSOR on page 223)