

CONDON STATE PAULING FLD (3S9) 1 NE UTC-8(-7DT) N45°14.79' W120°09.99'

SEATTLE
L-13A

2911 B NOTAM FILE MMV

RWY 07-25: H3500X60 (CONC) S-12 MIRL

RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Road.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: LGT ACTIVATE REIL Rwy 07 and Rwy 25; MIRL Rwy 07-25, PAPI Rwy 07 and Rwy 25—CTAF.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Heavy AG ops Feb-Jun.


AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE DLS.

KLICKITAT (H) (H) VORW/DME 112.3 LTJ Chan 70 N45°42.82' W121°06.05' 104° 48.4 NM to fld. 3220/21E.



CORNELIUS

SKYPORT (4S4) 3 N UTC-8(-7DT) N45°34.96' W123°03.17'

SEATTLE

174 NOTAM FILE MMV

RWY 16-34: 2000X45 (TURF)

RWY 16: Trees. Rgt tfc.

RWY 34: Thld dsplcd 200'. Road.

AIRPORT REMARKS: Attended 1400-0400Z. Helicopter and ultralight ops prohibited. Rwy 16-34 rwy ends marked with half barrels. Rwy 34 dsplcd thld marked with L-shaped boards.

AIRPORT MANAGER: 503-648-9311

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 503-493-7545.