

CHRISTMAS VALLEY (62S) 1 SE UTC-8(-7DT) N43°14.18' W120°39.88'

KLAMATH FALLS
H-18, L-11A

4320 B NOTAM FILE MMV

RWY 07-25: H5200X60 (ASPH) S-12 MIRL

RWY 25: PAPI(P2L)—GA 3.0° TCH 39'.

SERVICE: LGT ACTIVATE MIRL Rwy 07-25 and PAPI Rwy 25—CTAF.

AIRPORT REMARKS: Unattended. Remote ctdl actv in vcnty.

AIRPORT MANAGER: 541-576-2216

COMMUNICATIONS: CTAF/UNICOM 122.8


CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.

LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57'

W120°30.43' 332° 45.1 NM to fld. 7465/19E.

COMM/NAV/WEATHER REMARKS: UNICOM monitored irregularly.



CLEARWATER

TOKETEET STATE (3S6) 2 S UTC-8(-7DT) N43°13.41' W122°25.27'

KLAMATH FALLS

3361 NOTAM FILE MMV

RWY 11-29: 5350X60 (TURF) 2.4% up SE

RWY 11: Trees.

RWY 29: Trees.

AIRPORT REMARKS: Unattended. Arpt CLOSED from 1 Nov-1 May. Elk, deer and turkey on and invof arpt. Arpt on West side of Cascades and affected by wx West. Best info on arpt thru US Forest svc Roseburg, or lcl FBO at Roseburg. Rwy 11-29 graded, 60' wide, shoulders rough and rutted. Rwy 11-29 has +120' trees 250' either side of centerline. Rwy 11-29 thlds outlined with white tires. Trees 4'-30' along south side of rwy within 50' of centerline. Sfc conds not rptd.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

COLUMBIA GORGE RGNL/THE DALLES MUNI (See THE DALLES on page 177)

COLUMBIA N45°35.32' W122°36.68' NOTAM FILE PDX.

SEATTLE

(H) TACAN 109.2 CBU Chan 29 at Portland Intl. 22/20E.

H-18, L-1C

TACAN unusable:

020°-030° byd 30 NM blo 9,500'

030°-050° byd 20 NM blo 9,500'

100°-140° byd 65 NM blo 18,000'

120°-130° byd 15 NM blo 8,500'

155°-250° byd 15 NM blo 10,500'

250°-270° byd 20 NM blo 8,500'

DME unusable:

100°-140° byd 65 NM blo 18,000'