248 WASHINGTON

MEAD FLYING SERVICE (7ØS) 1 N UTC-8(-7DT) N47°47.23′ W117°21.49′

1905 TPA-2505(600) NOTAM FILE SEA

RWY 16-34: H2481X30 (ASPH)

RWY 16: Trees. RWY 34: Trees.

AIRPORT REMARKS: Unattended. No winter maintenance.

AIRPORT MANAGER: 253-880-7805 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2522

MEARS FLD (See CONCRETE on page 227)

## MFTALINE FALLS

**SULLIVAN LAKE STATE** (Ø9S) 3 SE UTC-8(-7DT) N48°50.45′ W117°17.04′

SEATTLE

SFATTI F

2614 NOTAM FILE SEA RWY 16-34: 1765X100 (TURF)

RWY 16: Trees.

RWY 34: Sign.

AIRPORT REMARKS: Unattended. Arpt clsd 1 Oct-1 June exc for apvd mil and public safety/law enforcement helicopter ops. Vehicles, pedestrians, and animals on and invof arpt. Watch for gnd squirrel holes in rwy. Rwy 16–34 sfc rough. Trees both sides in transition sfcs. Ctc WA State Aviation Division 360–709–8015 or 1–800–552–0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800–258–5990. Gnd drops rapidly byd Rwy 16–34 ends. Rwy marked with reflectors dur dates arpt is open. 2 wind socks, one on each rwy end.

AIRPORT MANAGER: (360) 618-2477
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

METHOW VALLEY STATE (See WINTHROP on page 287)

## MONROE

FIRST AIR FLD (W16) 2 NW UTC-8(-7DT) N47°52.28′ W121°59.71′

SEATTLE

50 NOTAM FILE SEA

**RWY 07–25:** H2087X34 (ASPH) RWY LGTS(NSTD)

RWY 07: P-line. Rgt tfc.

RWY 25: Thid dsplcd 500'. Trees.

SERVICE: S4 LGT SS-SR. Solar powered lighting.

AIRPORT REMARKS: Attended Oct-Mar 1700Z‡-dark, Apr-Sept 1700-0300Z‡. Parachute Jumping. Tran tie downs have no ropes, pilots must supply own. Additional tran parking avbl SE corner of rwy. Rwy 25 acft parked in primary sfc. Rwy 07 numbers 200´E of dsplod thr; numbers only; no cntrln. Word "MONROE" painted midfield on rwy. Rwy 07-25 markings are faded.

AIRPORT MANAGER: 425-239-8791 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

## MORTON

STROM FLD (39P) 0 SE UTC-8(-7DT) N46°33.02′ W122°16.00′

SEATTLE

941 B NOTAM FILE SEA RWY 07–25: H1810X40 (ASPH)

**RWY 07:** Thid dsplcd 200'. P–line.

RWY 25: Trees.

SERVICE: LGT ACTIVATE MIRL Rwy 07–25 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Trees near rwy. Trees, stream and brush in prim sfc. Deer and elk on and invof rwy. Ditch parallel rwy on Eastside. Rwy 07–25 markings faded. Rwy 07–25 wdspr raveling and alligator cracking.

AIRPORT MANAGER: (360) 496-5210 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.