

BESSEMER (EKY)(KEKY) 3 SE UTC-6(-5DT) N33°18.76' W86°55.58'

700 B NOTAM FILE ANB

RWY 05-23: H6007X100 (ASPH) S-60, D-60 HIRL

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 60'.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Ground.

SERVICE: S4 **FUEL** 100LL, JET A+ **OX** 3, 4 **LGT** ACTIVATE REIL Rwy 05 and Rwy 23; HIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Attended 1400-0000Z†. Fee for after hrs svc call 205-835-1415. Rwy 05-23 markings faded.

AIRPORT MANAGER: (205) 835-1415

WEATHER DATA SOURCES: AWOS-3PT 118.825 (205) 424-3127.

COMMUNICATIONS: CTAF/UNICOM 123.0

® **BIRMINGHAM APP/DEP CON** 124.9

CLNC DEL 123.75

CLEARANCE DELIVERY PHONE: For CD ctc Birmingham Apch at (205) 769-3907.

RADIO AIDS TO NAVIGATION: NOTAM FILE ANB.

BROOKWOOD (L) VORTACW 111.0 OKW Chan 47 N33°14.27'

W87°14.99' 075° 16.9 NM to fld. 655/OE.

VOR unusable:

138°-052°

DME unusable:


345°-040° byd 35 NM blo 3,000'

ILS/DME 111.75 I-EKY Chan 54(Y) Rwy 05. Glideslope unusable byd 4° right of course.

ATLANTA

H-6K, 9A, 12F, L-18H

IAP



BIBB CO (See CENTREVILLE on page 41)

BILL PUGH FLD (See RUSSELLVILLE on page 72)