

**GILA BEND AF AUX** (GXF)(KGXF) AF 3 S UTC-7 N32°53.27' W112°43.18'  
**AIRSPACE: CLASS D** svc 1430-0630Z Mon-Fri, 1500-2359Z wkend, clsd hol; other times CLASS G.

**PHOENIX**  
**H-4J, L-5B**

**GILA BEND MUNI** (E63) 2 E UTC-7 N32°57.61' W112°40.42'  
 789 B TPA—1589(800) NOTAM FILE PRC  
**RWY 04-22:** H5200X75 (ASPH) S-12.5 MIRL 0.3% up NE  
**RWY 04:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.  
**RWY 22:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.

**PHOENIX**  
**H-4J, L-5B, A**

**SERVICE:** FUEL 100LL LGT Actvt MIRL Rwy 04-22—CTAF. CTAF lighting OTS indef. Airport lighted windsock out of service indef. Airport beacon out of service indef. Intens Rwy Lights: Rwy 04-22 and twy lighting system out of service indef.

**AIRPORT REMARKS:** Unattended. 100LL self svc H24 with credit card. Rwy 04-22 primary sfc, +5-20 ft brush and trees, 100-125 ft S of cntrln. Area parl rwy narrows to 30' at culvert. NOTE: See Special Notices—Restricted Area R-2305, Gila Bend, Arizona Transit Information.

**AIRPORT MANAGER:** 623-810-4662

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**RCO** 122.1R 116.6T (PRESCOTT RADIO)

**CLEARANCE DELIVERY PHONE:** For CD ctc Luke Apch at 623-856-7361. If una ctc Albuquerque ARTCC at 505-856-4861.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PRC.

**(VH) (H) VORTAC** 116.6 GBN Chan 113 N32°57.38'  
 W112°40.46' at fld. 790/14E.

TACAN AZIMUTH unusable:  
 360°-010° byd 25 NM

VOR unusable:

091°-101° byd 40 NM blo 18,000'  
 102°-114° byd 40 NM blo 6,500'  
 102°-114° byd 53 NM blo 15,000'  
 102°-114° byd 79 NM  
 115°-189° byd 40 NM  
 211°-213° byd 40 NM  
 287°-292° byd 40 NM  
 293°-303° byd 40 NM blo 18,000'  
 304°-331° byd 40 NM  
 352°-090° byd 40 NM

