

GATTIS STRIP (See WASILLA on page 262)**GIRDWOOD** (AQY) 3 NE UTC-9(-8DT) N60°58.14' W149°07.16'

ANCHORAGE

164 NOTAM FILE ENA

RWY 02-20: 2095X60 (GRVL) 1.4% up N**RWY 02:** Brush.**RWY 20:** Brush.

AIRPORT REMARKS: Unattended. Rwy condition not monitored. 200' safety area at each end Rwy 02-20. Segmented circle overgrown. Seasonal hang glider and parasail activity 2 NM NE of arpt during daylight hours. Paragliding activity on arpt. Cable 100' AGL runs from new hotel to roundhouse. Rwy 02 and Rwy 20 thlds marked by reflectors. Rwy edges unmarked.

AIRPORT MANAGER: 907-783-2232**COMMUNICATIONS:** CTAF 122.9**RCO** 122.15 (KENAI RADIO)**RADIO AIDS TO NAVIGATION:** NOTAM FILE ANC.

ANCHORAGE (H) VOR/DME 113.15 TED Chan 78(Y) N61°10.07' W149°57.61' 098° 27.3 NM to fld. 93/18E.

VOR unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

DME unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'


096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

196°-206° byd 25 NM blo 3,500'

206°-211° byd 25 NM blo 4,000'

211°-221° byd 25 NM blo 3,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.**GLACIER CREEK** (KGZ) 0 N UTC-9(-8DT) N61°27.31' W142°22.86'

ANCHORAGE

2380 NOTAM FILE ENA

RWY 11-29: 1400X15 (GRVL)**RWY 11:** Trees.**RWY 29:** Tree.

AIRPORT REMARKS: Unattended. Rwy condition not monitored. Recommend visual inspection prior to ldg. Rwy 11-29 in steep mountain canyon and subject to turbulent winds. Rwy 11-29 sfc rough with rocks to 8" diameter ruts down rwy center, rwy undulates. Rwy 15' wide gravel path. Brush to 36" both sides. Rwy 11-29 not recommended for tri-cycle general acct.

AIRPORT MANAGER: 907-822-7240**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE ORT.

NORTHWAY (H) VORTACW 116.3 ORT Chan 110 N62°56.83'

W141°54.76' 165° 90.7 NM to fld. 1779/24E.


TACAN AZIMUTH unusable:

335°-030° byd 30 NM blo 10,500'

DME unusable:

335°-030° byd 30 NM blo 10,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

**GLACIER RIVER** N60°29.93' W145°28.47' NOTAM FILE CDV.

ANCHORAGE

NDB (HW) 404 GCR at Merle K (Mudhole) Smith. 58/17E.

L-1A, 3E, 4H

GLENNALLEN N62°11.73' W145°28.06' NOTAM FILE GKN.

ANCHORAGE

NDB (HW) 248 GLA 153° 2.5 NM to Gulkana. 1619/19E.

L-1A, 3E

GOLD KING CREEK (See FAIRBANKS on page 106)