

**GLACIER CREEK** (KGZ) 0 N UTC-9(-8DT) N61°27.31' W142°22.86'

ANCHORAGE

2380 NOTAM FILE ENA

RWY 11-29: 1400X15 (GRVL)

RWY 11: Trees.

RWY 29: Tree.

**AIRPORT REMARKS:** Unattended. Rwy condition not monitored.

Recommend visual inspection prior to ldg. Rwy 11-29 in steep mountain canyon and subject to turbulent winds. Rwy 11-29 sfc rough with rocks to 8" diameter ruts down rwy center, rwy undulates. Rwy 15' wide gvl path. Brush to 36" both sides. Rwy 11-29 not recommended for tri-cycle general acft.

**AIRPORT MANAGER:** 907-822-7240**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE ORT.

**NORTHWAY (H) VORTACW** 116.3 ORT Chan 110 N62°56.83' W141°54.76' 171° 90.7 NM to fld. 1779/18E.


TACAN AZIMUTH unusable:

335°-030° byd 30 NM blo 10,500'

DME unusable:

335°-030° byd 30 NM blo 10,500'

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.

**GLACIER RIVER** N60°29.93' W145°28.47' NOTAM FILE CDV.

ANCHORAGE

NDB (HW) 404 GCR at Merle K (Mudhole) Smith. 55/17E.

L-1A, 3E, 4H

**GLENNALLEN** N62°11.73' W145°28.06' NOTAM FILE GKN.

ANCHORAGE

NDB (HW) 248 GLA 153° 2.5 NM to Gulkana. 1619/19E.

L-1A, 3E

**GOLD KING CREEK** (See FAIRBANKS on page 111)**GOLDEN HORN LODGE SPB** (3Z8) 1 NW UTC-9(-8DT) N59°44.82' W158°52.48'

KODIAK

91 NOTAM FILE DLG

WATERWAY NW-SE: 5000X1500 (WATER)

**AIRPORT REMARKS:** Attended Jun-Oct.**AIRPORT MANAGER:** 907-842-8260**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE DLG.

**DILLINGHAM (H) VORW/DME** 116.4 DLG Chan 111 N58°59.65' W158°33.13' 333° 46.4 NM to fld. 81/15E.

**GOLOVIN** (GLV)(PAGL) 0 N UTC-9(-8DT) N64°33.03' W163°00.43'

NOME

65 B NOTAM FILE GLV

H-1A, 2J, L-3C, 4H

RWY 03-21: 4000X75 (GRVL) MIRL 0.6% up NE

IAP

RWY 03: PAPI(P4L)—GA 3.0° TCH 26'.

**SERVICE:** LGT ACTIVATE PAPI Rwy 03; MIRL Rwy 03-21 and rot bcn—CTAF. Rwy 03 PAPI unusbl byd 4 NM due to terrain.

**AIRPORT REMARKS:** Unattended. Rwy cond not monitored, recommend visual inspection prior to ldg. Area depressed about 2 ft on the west side of the rwy midfield aprx 10 ft inside lights and 20 ft outside.

**AIRPORT MANAGER:** 907-443-2500**WEATHER DATA SOURCES:** ASOS 135.750 (907) 779-2228. (WX CAM)**COMMUNICATIONS:** CTAF 122.9

RCO 122.05 (NOME RADIO)

ANCHORAGE CENTER APP/DEP CON 133.3


**RADIO AIDS TO NAVIGATION:** NOTAM FILE OME.

**NORTON BAY NDB (HW)** 263 OAY N64°41.73' W162°03.82' 238° 25.9 NM to fld. 13E.

NDB unusable:

Byd 35 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Nome FSS dial 1-800-478-8400. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

**GOODING LAKE SPB** (See PALMER on page 203)