

LAWING (9Z9) 1 N UTC-9(-8DT) N60°24.71' W149°22.16'

484 NOTAM FILE ENA

RWY 15-33: 2355X60 (GRVL) 0.6% up NW

RWY 15: Trees.

RWY 33: Tree.

AIRPORT REMARKS: Unattended. State maintenance on irregular basis. Rwy cond not monitored, recommend visual inspection prior to using. Rwy undulates, soft during spring thaw. Ruts on east side. Overrun slopes down 5%. All terrain vehicles using rwy as a road. Rwy 15-33 thld panels damaged. Rwy 15 edges not marked. Windssock is below treeline and may be unreliable.

AIRPORT MANAGER: 907-288-2428


COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.

KENAI (H) VOR/DME 117.6 ENA Chan 123 N60°36.88' W151°11.71' 083° 55.5 NM to fld. 115/19E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

ANCHORAGE



LAWRENCE AIRSTRIP (See WASILLA on page 260)

LAZY BAY

ALITAK SPB (ALZ) 0 S UTC-9(-8DT) N56°53.97' W154°14.87'

00 NOTAM FILE ENA

WATERWAY NE-SW: 10000X1000 (WATER)

SEAPLANE REMARKS: Unattended. E-W prevailing winds. Subject to swells in Easterly winds. Acft beaching area is a gravel area east side of cannery. Dock in front of beaching area is hazardous to acft. Ltd para-glider activity during summer months. Heavy bird activity noted in area.

AIRPORT MANAGER: 206-285-6800

COMMUNICATIONS: CTAF 122.8

RADIO AIDS TO NAVIGATION: NOTAM FILE ADQ.

KODIAK (H) VOR/DME 117.1 ODK Chan 118 N57°46.50' W152°20.39' 216° 81.4 NM to fld. 133/14E.

VOR unusable:

190°-310° byd 15 NM blo 12,000'

DME unusable:


154°-265° byd 15 NM blo 12,000'

266°-305°

306°-341° byd 15 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

KODIAK



LENA POINT N58°23.30' W134°45.72'

RCO —122.25 (JUNEAU FSS)

JUNEAU

L-1B