

MC KINLEY NTL PARK (INR)(PAIN) 2 NE UTC-9(-8DT) N63°43.96' W148°54.64' ANCHORAGE
1720 NOTAM FILE INR
RWY 16-34: 3000X68 (GRVL)

RWY 16: Trees.
RWY 34: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Freq pedestrian and wildlife tfc on rwy. No ovrn at either rwy end. Canyon South and West of arpt subject to strong downdrafts. Winter maintenance. Coml or business use of this airstrip is prohibited exc under permit with National Park Service. Pvt rotorwing use prohibited, exc in case of emergencies. All tfc patterns to east side due to terrain cnc. Rwy 16-34 marked with damaged and faded cones. Acft parking along sides of Rwy 16-34 has reduced usable width to 68'. Rwy 16-34 grass encroachment on both sides of rwy.

AIRPORT MANAGER: 907-683-9581

WEATHER DATA SOURCES: AWOS-3P 135.75 (907) 683-1673. (WX CAM)
COMMUNICATIONS: CTAF 122.9


MCKINLEY PARK RCO 122.1 (FAIRBANKS RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE ENN.

NENANA (H) VORTACW 115.8 ENN Chan 105 N64°35.40'
W149°04.37' 154° 51.8 NM to fld. 1600/21E.

VOR portion unusable:
086°-096° byd 34 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516. Freqs 122.725 north, 123.65 south is designated for inter acft communication in Denali National Park.



MEKORYUK (MYU)(PAMY) 3 W UTC-9(-8DT) N60°22.34' W166°16.21' BETHEL
53 B NOTAM FILE MYU

RWY 05-23: 3001X75 (GRVL) MIRL

RWY 05: VASI(V4L)—GA 3.0° TCH 28'. Road.

RWY 23: VASI(V4R)—GA 3.0° TCH 29'. Road.

SERVICE: LGT ACTVT VASI Rwy 05 and 23; MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Animals occasionally on rwy. Rwy 05-23 shallow ruts with ponding after rain. Windssock unreliable. Rwy 05 and Rwy 23 NSTD markings, rwys marked with reflective cones and thld panels.

AIRPORT MANAGER: (907) 543-2498

WEATHER DATA SOURCES: AWOS-3P 123.9 (907) 827-8135. (WX CAM)

COMMUNICATIONS: CTAF 122.9

NANWAK RCO 122.0 (KENAI RADIO)


ANCHORAGE CENTER APP/DEP CON 124.5

RADIO AIDS TO NAVIGATION: NOTAM FILE MYU.

NANWAK NDB/DME (HW) 323 AIX Chan 76 N60°23.12'
W166°12.86' 232° 1.8 NM to fld. 38/13E.

NDB/DME unusable:
115°-225° byd 30 NM

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



MERLE K (MUDHOLE) SMITH (See CORDOVA on page 89)

MENTASTA N62°52.81' W143°35.53'
RCO —121.4 (NORTHWAY FSS)

ANCHORAGE
L-1A, 3E

MERRILL FLD (See ANCHORAGE on page 44)

MERTARVIK QUARRY ROAD LANDING STRIP (FØ2)(PFME) 1 W UTC-9(-8DT) N60°49.10' BETHEL
W164°31.14'

70 NOTAM FILE EIL Not insp.

RWY 08-26: 2000X35 (GRVL)

AIRPORT MANAGER: 907-237-6095

COMMUNICATIONS: CTAF 122.9