

MCCARTHY

JAKES BAR (AK0) 13 SE UTC-9(-8DT) N61°13.13' W142°53.47'

ANCHORAGE

1074 NOTAM FILE ENA

RWY 10-28: 1000X25 (GRVL) 0.7% up SE

RWY 10: Tree.

RWY 28: Tree.

AIRPORT REMARKS: Unattended. Rwy suitable only for conventional geared acft. Rwy condition not monitored, recommend visual inspection prior to landing. Rwy is an unimproved river gravel bar. Subject to turbulence in any wind. Rwy surface very rough. Rocks up to 15" in diameter. Grass up to 12" over entire surface.


AIRPORT MANAGER: 907-822-7240

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE GKN.

GULKANA (H) VOR/DME 115.6 GKN Chan 103 N62°09.23' W145°26.84' 109° 92.2 NM to fld. 1549/17E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



MCCARTHY (15Z)(PAMX) 1 NE UTC-9(-8DT) N61°26.27' W142°54.15'

ANCHORAGE

1533 NOTAM FILE MXY

RWY 01-19: 3501X60 (GRVL-DIRT) 0.3% up S

RWY 01: Brush.

RWY 19: Brush.

AIRPORT REMARKS: Unattended. Irregular winter maintenance. Rwy condition not maintained, recommend visual inspection prior to landing. Wildlife invof rwy. Apch to Rwy 01 over old McCarthy Arpt.


AIRPORT MANAGER: 907-822-3222

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE GKN.

GULKANA (H) VOR/DME 115.6 GKN Chan 103 N62°09.23' W145°26.84' 103° 84.3 NM to fld. 1549/17E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



L-1A, 3E

SWIFT CREEK (AK31) PVT 3 SW UTC-9(-8DT) N61°24.67' W143°00.07'

1225 NOTAM FILE Not insp.

RWY 16-34: 2000X35 (TURF)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Unattended. Creek and sharp ditches close to rwy S approximately 1/2 mile.

AIRPORT MANAGER: 907-521-0178

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.