

NORTHWAY (ORT)(PAOR) 0 S UTC-9(-8DT) N62°57.67' W141°55.69'

ANCHORAGE

1720 B LRA NOTAM FILE ORT

H-1B, L-1A, 3E

RWY 05-23: H5100X100 (ASPH-GRVD) MIRL

IAF

RWY 05: PAPI(P4L)—GA 3.0° TCH 39'. Trees.**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 36'. Trees.**SERVICE:** LGT ACTVT REIL Rwy 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored; recommend visual inspection prior to landing. Pilots of acft arriving ORT/PAOR or Yarger Lake from foreign countries must receive permission to land from U.S. customs by phone 907-774-2242/2252 at least two hrs prior to arrival. Permission is not normally granted outside 1800-0000Z± daily. In addition an EAPIS manifest is also required to be filed electronically prior to departure. Floatplane customs svc avbl at Yarger Lake-8 NM east. Frequent strong and variable crosswind. Cold temperature airport. Altitude correction required at or below -42C. Snow removal operations during winter-monitor CTAF. Ski strip parallel and adjacent to apch end Rwy 23 NW side.

AIRPORT MANAGER: 907-883-5128**WEATHER DATA SOURCES:** ASOS 135.4 (907) 778-2282. (WX CAM)**COMMUNICATIONS:** CTAF 123.6

FSS ORT (NORTHWAY) May 1-Sep 30 1715-0245Z±; OT ctc

Fairbanks FSS.

NORTHWAY RADIO 121.5 122.2 122.65 123.6 243.0 (LAA 123.6)**ANCHORAGE CENTER APP/DEP CON** 126.55 323.0**SUAIS** 125.3 126.3 (1-800-758-8723)**AIRSPACE:** CLASS E svc continuous.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ORT.

(H) VORTACW 116.3 ORT Chan 110 N62°56.83' W141°54.76' at fld. 1779/24E.

TACAN AZIMUTH unusable:


335°-030° byd 30 NM blo 10,500'

DME unusable:

335°-030° byd 30 NM blo 10,500'

NABESNA NDB (HW) 390 AES N62°56.96' W141°54.59' at fld. 1715/20E.

COMM/NAV/WEATHER REMARKS: FSS on arpt 1 May-30 Sep. LC to Northway FSS dial 778-2219. Northway FSS toll free number 1-800-478-6611. For a toll free call to Fairbanks FSS dial 1-866-248-6516. Contract Wx observation is avbl when ORT FSS clsd on 133.55 or phone 907-778-2240.

**NORTON BAY** N64°41.73' W162°03.82' NOTAM FILE OME.

NOME

NDB (HW) 263 OAY at Moses Point. 13E.

L-3C, 4H

NDB unusable:

Byd 35 NM

NUGGET BENCH (33AK) PVT 1 SE UTC-9(-8DT) N62°31.04' W150°56.72'

ANCHORAGE

2010 NOTAM FILE

RWY 01-19: 1240X38 (GRVL)**RWY 01:** Brush.**RWY 19:** Brush.

AIRPORT REMARKS: Unattended. Rwy 01-19 width varies 38 to 81'. 5' high brush 20' from approach end of Rwy 19.

AIRPORT MANAGER: 907-279-1560**COMMUNICATIONS:** CTAF 123.65**RADIO AIDS TO NAVIGATION:** NOTAM FILE TKA.**TALKEETNA (H) VOR/DME** 116.2 TKA Chan 109 N62°17.90'

W150°06.32' 281° 26.9 NM to fld. 568/19E.

VOR unusable:

277°-297° byd 30 NM blo 12,000'

DME unusable:

057°-087° byd 30 NM blo 13,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-800-864-1737.

