


SOLDOTNA HOSPITAL H HELIPORT (SD1) 1 NW UTC-9(-8DT) N60°29.56' W151°04.74' ANCHORAGE
 99 NOTAM FILE ENA
HELIPAD H1: H80X80 (ASPH) PERIMETER LGTS
SERVICE: LGT Helipad H1 perimeter lgts.
HELIPORT REMARKS: Attended continuously. No ops over hospital.
AIRPORT MANAGER: 907-714-4404
COMMUNICATIONS: CTAF 122.9
RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.
KENAI (H) (H) VOR/DME 117.6 ENA Chan 123 N60°36.88' W151°11.71' 136° 8.1 NM to fld. 115/19E.
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



SOLOY STRIP (See WASILLA on page 260)

SONGLO VISTA (See TALKEETNA on page 236)

SOUTH NAKNEK NR 2 (WSN)(PFW) 1 SSW UTC-9(-8DT) N58°42.13' W157°00.16' KODIAK
 162 B NOTAM FILE WSN L-21, 3C
RWY 13-31: 3314X60 (GRVL-DIRT) HIRL IAP
RWY 13: VASI(V2L)—GA 3.0° TCH 25'. Brush.
RWY 31: Thld dsplcd 559'. Brush.
RWY 05-23: 2264X60 (GRVL-DIRT) HIRL 1.5% up SW
RWY 05: Brush.
RWY 23: Brush.
SERVICE: LGT ACTVT VASI Rwy 13; HIRL Rwy 05-23 and 13-31—CTAF.
AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Be alert: vehicles, moose and bears invof and on rwys. Heavy acft tfc between South Naknek and Naknek aprts less than two miles apart. Loose rocks on Rwy 13-31. Twy slopes downhill to the northwest. No line of sight between end of twy and Rwy 13-31. Relocated Rwy 31 thld marked by short cones and lgts.
AIRPORT MANAGER: 907-246-3325
WEATHER DATA SOURCES: AWOS-3P 121.575 (907) 868-7348. (WX CAM)
COMMUNICATIONS: CTAF 122.9
 Ⓡ ANCHORAGE CENTER APP/DEP CON 124.8
RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.
KING SALMON (H) (H) VORTACW 112.8 AKN Chan 75 N58°43.48' W156°45.14' 244° 7.9 NM to fld. 95/16E.
 TACAN antenna offset 150' se
 TACAN AZIMUTH unusable:
 130°-140° byd 13 NM blo 4,000'
 130°-140° byd 30 NM
 332°-348° byd 19 NM blo 5,000'
 DME unusable:
 332°-348° byd 19 NM blo 5,000'
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

