

SQUAW HARBOR SPB (36H) 0 S UTC-9(-8DT) N55°14.00' W160°33.12'

COLD BAY

00 NOTAM FILE CDB

WATERWAY ALL-WAY: 5000X5000 (WATER)

SEAPLANE REMARKS: Unattended. Operating area in Baralof Bay; unable to beach due to large rocks. Dock used for boat docking. Dock unsuitable for aircraft use.

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE SDP.

BORLAND NDB/DME (HW) 390 HBT Chan 79 N55°18.94'

W160°31.10' 182° 5.1 NM to fld. 130/11E.

NDB unusable:

304°-354° byd 16NM

DME unusable:

034°-134° byd 6NM

184°-264° byd 27 NM blo 14,000'

184°-264° byd 6 NM blo 10,000'

354°-034° byd 22 NM blo 18,000'


354°-034° byd 27NM

354°-034° byd 6 NM blo 10,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Cold Bay FSS dial

1-800-478-7250. For a toll free call to Kenai FSS dial

1-866-864-1737.



STAMPEDE (See KANTISHNA on page 137)

STEAMBOAT BAY SPB (WSB)(POWS) 0 NE UTC-9(-8DT) N55°31.78' W133°38.50'

KETCHIKAN

00 NOTAM FILE KTN

WATERWAY N-S: 6000X2000 (WATER)

SEAPLANE REMARKS: Unattended. High mountains all sides except entrance: one way ops, no south ops, subject to heavy swells and squirrely winds. No facilities. Large ocean swells common in bay, exposed to north wind.

AIRPORT MANAGER: 253-225-4256

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE SIT.

LEVEL ISLAND (H) VORW/DME 116.5 LVD Chan 112 N56°28.06'

W133°04.99' 179° 59.5 NM to fld. 98/20E.

VOR unusable:

038°-098° byd 35 NM blo 9,000'

098°-138° byd 25 NM blo 7,000'

168°-208° byd 35 NM blo 6,000'

268°-328° byd 25 NM blo 9,000'

328°-358° byd 30 NM blo 7,000'

328°-358° byd 35 NM blo 8,000'

358°-038° byd 35 NM blo 12,000'

wx cam

DME unusable:

038°-098° byd 35 NM blo 9,000'

098°-138° byd 25 NM blo 7,000'

168°-208° byd 35 NM blo 6,000'

268°-328° byd 25 NM blo 9,000'

328°-358° byd 30 NM blo 7,000'

328°-358° byd 35 NM blo 8,000'

358°-038° byd 35 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For a LC to Ketchikan FSS dial 225-9481. For a LC to Juneau FSS dial 789-7380.

