

SOLDOTNA HOSPITAL H HELIPORT (SD1) 1 NW UTC-9(-8DT) N60°29.56' W151°04.74' ANCHORAGE

99 NOTAM FILE ENA

HELIPAD H1: H80X80 (ASPH) PERIMETER LGTS

SERVICE: LGT Helipad H1 perimeter lgts.

HELIPORT REMARKS: Attended continuously. No ops over hospital.


AIRPORT MANAGER: 907-714-4404

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.

KENAI (H) VOR/DME 117.6 ENA Chan 123 N60°36.88'
W151°11.71' 136° 8.1 NM to fld. 115/19E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



SOLOY STRIP (See WASILLA on page 268)

SONGLO VISTA (See TALKEETNA on page 244)

SOUTH NAKNEK NR 2 (WSN)(PFW) 1 SSW UTC-9(-8DT) N58°42.13' W157°00.16'

162 B NOTAM FILE WSN

RWY 13-31: 3314X60 (GRVL-DIRT) HIRL

RWY 13: VASI(V2L)—GA 3.0° TCH 25'. Brush.

RWY 31: Thld dsplcd 559'. Brush.

RWY 05-23: 2264X60 (GRVL-DIRT) HIRL 1.5% up SW

RWY 05: Brush.

RWY 23: Brush.

SERVICE: LGT ACTVT VASI Rwy 13; HIRL Rwy 05-23 and 13-31—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Be alert: vehicles, moose and bears invof and on rwys. Heavy acft tfc between South Naknek and Naknek aprts less than two miles apart. Loose rocks on Rwy 13-31. Twy slopes downhill to the northwest. No line of sight between end of twy and Rwy 13-31. Relocated Rwy 31 thld marked by short cones and lgts.

AIRPORT MANAGER: 907-246-3325

WEATHER DATA SOURCES: AWOS-3P 121.575 (907) 868-7348. (WX CAM)

COMMUNICATIONS: CTAF 122.9

ANCHORAGE CENTER APP/DEP CON 124.8 354.0

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

KING SALMON (H) VORTAC 112.8 AKN Chan 75 N58°43.48' W156°45.14' 244° 7.9 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'

130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

KODIAK

L-21, 3C

IAP

