

TALKEETNA (TKA)(PATK) 1 E UTC-9(-8DT) N62°19.28' W150°05.56'
365 B NOTAM FILE TKA

ANCHORAGE
L-3D, 4F
IAF

RWY 01-19: H3500X75 (CONC-NONE) MIRL

RWY 01: VASI(V4R)—GA 3.0° TCH 23'. Trees.

RWY 19: VASI(V4L)—GA 3.0° TCH 23'. Rgt tfc.

SERVICE: S4 **FUEL** 100LL, JET A, A+ **LGT** ACTIVATE MIRL Rwy

01-19—CTAF. VASI Rwy 01 and Rwy 19 opr continuously.

AIRPORT REMARKS: Attended Apr–Nov, Mon–Thu 0000–1030Z‡, Dec–Mar, Sun–Sat 0000–1030Z‡. FBO fuel 24 hrs. Jet fuel avbl Mon–Fri 1600–0200Z‡. Jet A fuel is lctd off arpt. Prior arrangements for jet fuel requested to avoid delays. 907-733-2620. After hrs fuel only avbl with prior arrangements. BE ALERT: walking on active taxiway/aprons is not auth. Helo tfc using fuel/maint fac remain south of FSS and fly direct from rotg bcn to avoid damage to parked acft. Rwy 01-19 clsd to acft over 12,500 lbs; ctc amgr 907-733-2278. Rwy condition not monitored recommend visual inspection prior to using. Seaplane ops 3/4 mile SE Talkeetna arpt. Recommend acft ops to and from Christiansen Lake remain east of lake. Be alert CTAF procedures highly recommended due to village tfc pattern. Arpt has designated transient acft parking avbl. New helicopter ops area on North ramp. See Section C: notices, for tfc pattern info.

AIRCRAFT MANAGER: 907-733-2278

WEATHER DATA SOURCES: ASOS 135.2 (907) 733-1637. (WX CAM)

COMMUNICATIONS: CTAF 123.6 ATIS 135.2 UNICOM 123.0

FSS TKA (TALKEETNA) Sep 15–Apr 14 1700-0245Z‡, Apr 15–Sep 14 1700-0500Z‡; OT ctc Kenai FSS.

TALKEETNA RADIO 121.5 122.2 123.6 (LAA 123.6)

RCO 121.5 122.2 123.6 (KENAI RADIO)

ANCHORAGE CENTER APP/DEP CON 125.55 254.3

AIRSPACE: CLASS E svc 1700-0500Z‡; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE TKA.

(H) **VOR/DME** 116.2 TKA Chan 109 N62°17.90' W150°06.32' 355° 1.4 NM to fld. 568/19E.

VOR unusable:


277°-297° byd 30 NM blo 12,000'

DME unusable:

057°-087° byd 30 NM blo 13,000'

PETERS CREEK NDB (HW) 305 PEE N62°19.86' W150°05.78' at fld. 359/16E.

COMM/NAV/WEATHER REMARKS: Talkeetna FSS telephone 733-2277. AFIS opr by Talkeetna FSS when open.



TAMGAS HARBOR SPB (See ANNETTE on page 49)

TANACROSS (TSG) 1 S UTC-9(-8DT) N63°22.44' W143°19.74'

ANCHORAGE
H-1B, L-1A, 3E

1559 NOTAM FILE ORT

RWY 06-24: H4963X150 (ASPH)

RWY 06: Trees.

RWY 24: Trees.

RWY 12-30: H4871X150 (ASPH) 0.3% up SE

RWY 12: Trees.

RWY 30: Trees.

AIRPORT REMARKS: Unattended. Fire crews and air operations during summer months. Rwy 06-24 not maintained during winter. Rwy 12-30 not maintained during winter. Rwy 06-24 sfc cracked, vegetation growing through asph. Rwy 12-30 sfc cracked, vegetation growing through asph. Rwy 30 apch—280' wide swath cut through trees. Rwy 24 apch—300' wide swath cut through trees.

AIRCRAFT MANAGER: (907) 474-2320

COMMUNICATIONS: CTAF 122.8

SUAS 125.3 126.3 (1-800-758-8723).

RADIO AIDS TO NAVIGATION: NOTAM FILE ORT.

NORTHWAY (H) VORTACW 116.3 ORT Chan 110 N62°56.83' W141°54.76' 280° 46.3 NM to fld. 1779/24E.

TACAN AZIMUTH unusable:

335°-030° byd 30 NM blo 10,500'

DME unusable:

335°-030° byd 30 NM blo 10,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Northway FSS dial 1-800-478-6611. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

