


TAKU HARBOR SPB (A43) 0 N UTC-9(-8DT) N58°04.15' W134°00.92' **JUNEAU**
 00 NOTAM FILE JNU
WATERWAY NE-SW: 3000X1000 (WATER)
SEAPLANE REMARKS: Unattended. Boats may dominate float, leaving no room for seaplanes.
AIRPORT MANAGER: (907)586-5255
COMMUNICATIONS: CTAF 122.9
COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.

TAKU LODGE SPB (TKL)(PFTK) 0 E UTC-9(-8DT) N58°29.38' W133°56.61' **JUNEAU**
 00 NOTAM FILE JNU
WATERWAY NE-SW: 5000X500 (WATER)
SEAPLANE REMARKS: Attended summer months dalgt hrs. Otters occupy the lodges entire float, arriving and departing at 15 min intervals. Mountains northwest and southeast. Shallow at low tides land in river channel; summer oprs only.
AIRPORT MANAGER: (907) 586-6275
COMMUNICATIONS: CTAF/UNICOM 123.05
COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.

TALKEETNA

BIRCH CREEK LANDING (51AK) PVT 6 SSE UTC-9(-8DT) N62°14.54' W150°03.95' **ANCHORAGE**
 400 NOTAM FILE Not insp.
RWY 16-34: 2500X75 (TURF)
AIRPORT REMARKS: Unattended. PPR before landing. All acct monitor and announce intentions on freq 123.6. Wind indicator SW of rwy. 200' cell 1/2 mile NW of rwy with white flashing lgts simultaneously. SPB ops on fish lake 1/2 mile N of rwy.
AIRPORT MANAGER: 907-355-4808
COMMUNICATIONS: CTAF 123.6
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

CHRISTIANSEN LAKE SPB (AK8) 1 SE UTC-9(-8DT) N62°18.80' W150°04.16' **ANCHORAGE**
 400 NOTAM FILE TKA
WATERWAY 14W-32W: 4000X1600 (WATER)
WATERWAY 04W-22W: 3800X2000 (WATER)
SERVICE: FUEL 100LL
SEAPLANE REMARKS: Attended continuously. All tfc remain east of SPB and over the lake. All traffic must use CTAF.
AIRPORT MANAGER: 907-733-4500
COMMUNICATIONS: CTAF 123.6
RADIO AIDS TO NAVIGATION: NOTAM FILE TKA.
TALKEETNA (H) VOR/DME 116.2 TKA Chan 109 N62°17.90' W150°06.32' 029° 1.4 NM to fld. 568/19E.
 VOR unusable:
 277°-297° byd 30 NM blo 12,000'
 DME unusable:
 057°-087° byd 30 NM blo 13,000'
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



SECLUDED LAKE (49AK) PVT 20 S UTC-9(-8DT) N62°01.47' W149°58.63' **ANCHORAGE**
 300 NOTAM FILE Not insp.
RWY 06-24: 2800X60 (GRVL)
AIRPORT REMARKS: Unattended. Trees 60' north and south of rwy centerline.
AIRPORT MANAGER: 907-235-5537
COMMUNICATIONS: CTAF 122.8
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

SONGLO VISTA (3AK3) PVT 15 NW UTC-9(-8DT) N62°33.83' W150°13.23' **ANCHORAGE**
 825 NOTAM FILE Not insp.
RWY 15-33: 2100X30 (GRVL)
AIRPORT REMARKS: Unattended. Irregular snow removal, recommend visual inspection prior to use. Surface could be soft during spring breakup. Rwy center is lower than rwy ends. Bear and moose occasionally on and invof arpt.
AIRPORT MANAGER: 907-733-8000
COMMUNICATIONS: CTAF 122.9
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.