

TOKSOOK BAY (OOK)(PA00) 1 NE UTC-9(-8DT) N60°32.48' W165°05.23'

71 B NOTAM FILE OOK

RWY 16-34: 3200X75 (GRVL-DIRT) MIRL 0.7% up N

RWY 16: REIL. PAPI(P4L)—GA 4.0° TCH 37'.

RWY 34: REIL. PAPI(P4R)—GA 3.0° TCH 30'.

SERVICE: LGT ACTVT REIL Rwy 16 and Rwy 34; PAPI Rwy 16 and Rwy 34; MIRL Rwy 16-34, and rotating bcn—CTAF. Rwy 16 PAPI unusbl byd 9 deg left of cntrln.

AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmdnd visual insp prior to use. Birds on and invof arpt. Vehicle and ATV tfc on rwy and ramp. Exp random turbulent winds.

AIRPORT MANAGER: (907) 543-2498

WEATHER DATA SOURCES: AWOS-3P 119.275 (907) 427-7004. (WX CAM)

COMMUNICATIONS: CTAF 122.9

KIPNUK RCO 122.6 (KENAI RADIO)

® ANCHORAGE CENTER APP/DEP CON 125.2


RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) (H) VORTACW 114.1 BET Chan 88 N60°47.09'

W161°49.46' 249° 97.4 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial

1-866-864-1737.



BETHEL

L-3B

IAP

TOLSONA LAKE SPB (58A) 0 N UTC-9(-8DT) N62°06.80' W146°02.46'

2000 NOTAM FILE ENA

WATERWAY NW-SE: 4000X1500 (WATER)

SERVICE: S4

SEAPLANE REMARKS: Unattended. Airstrip on east side of lake is private.

Public easement across pvt property to access Tolsona Lake. Wind sock is located at the NE corner of the lake.

AIRPORT MANAGER: 907-822-3433

COMMUNICATIONS: CTAF 122.9


RADIO AIDS TO NAVIGATION: NOTAM FILE GKN.

GULKANA (H) (H) VORW/DME 115.6 GKN Chan 103 N62°09.23'

W145°26.84' 245° 16.9 NM to fld. 1549/17E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial

1-866-864-1737.



ANCHORAGE