

**CHRISTIENSEN LAKE SPB** (AK8) 1 SE UTC-9(-8DT) N62°18.80' W150°04.16'

ANCHORAGE

400 NOTAM FILE TKA

**WATERWAY 14W-32W:** 4000X1600 (WATER)

**WATERWAY 04W-22W:** 3800X2000 (WATER)

**SERVICE:** FUEL 100LL

**SEAPLANE REMARKS:** Attended continuously. All tfc remain east of SPB and over the lake. All traffic must use CTAF.

**AIRPORT MANAGER:** 907-733-4500

**COMMUNICATIONS:** CTAF 123.6

**RADIO AIDS TO NAVIGATION:** NOTAM FILE TKA.

**TALKEETNA (H) VOR/DME** 116.2 TKA Chan 109 N62°17.90'

W150°06.32' 029° 1.4 NM to fld. 568/19E.

VOR unusable:


277°-297° byd 30 NM blo 12,000'

DME unusable:

057°-087° byd 30 NM blo 13,000'

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial

1-866-864-1737.



**SECLUDED LAKE** (49AK) PVT 20 S UTC-9(-8DT) N62°01.47' W149°58.63'

ANCHORAGE

300 NOTAM FILE Not insp.

**RWY 06-24:** 2800X60 (GRVL)

**AIRPORT REMARKS:** Unattended. Trees 60' north and south of rwy centerline.

**AIRPORT MANAGER:** 907-235-5537

**COMMUNICATIONS:** CTAF 122.8

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.

**SONGLO VISTA** (3AK3) PVT 15 NW UTC-9(-8DT) N62°33.83' W150°13.23'

ANCHORAGE

825 NOTAM FILE Not insp.

**RWY 15-33:** 2100X30 (GRVL)

**AIRPORT REMARKS:** Unattended. Irregular snow removal, recommend visual inspection prior to use. Surface could be soft during spring breakup. Rwy center is lower than rwy ends. Bear and moose occasionally on and invof arpt.

**AIRPORT MANAGER:** 907-733-8000

**COMMUNICATIONS:** CTAF 122.9

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.