

YUKON CHARLEY RIVERS**COAL CREEK** (L2Ø) 1 W UTC-9(-8DT) N65°18.69' W143°08.05'

DAWSON

867 NOTAM FILE FAI

L-4J

RWY 01-19: 3900X80 (GRVL) 0.3% up S**RWY 01:** Road.**RWY 19:** Road.

AIRPORT REMARKS: Unattended. Rwy 01-19 not maintained during winter and early spring. Rwy condition not monitored. Recommend visual inspection prior to using. Rwy 01-19 sfc very rough, rocks up to 6 inch. Rwy 01-19 is a dredged creek bottom sloping uphill north to south. 8 ft high dredge tailings on both sides full length of Rwy 01-19. Rwy 01-19 subject to erratic winds. Rwy located in valley. Rapidly rising terrain to the west and east. Watch for vehicles and pedestrians east edge of Rwy 01-19. Rwy 01-19 thld marked with cones and damaged reflective panels. Limited acft parking along west side near south end of Rwy 01-19. Large rocks in ramp and parking area, up to 18 inches.

AIRPORT MANAGER: 907-455-0646**COMMUNICATIONS:** CTAF 122.8

SUAS 125.3 126.3 (1-800-758-8723).

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.**YUKON RIVER** N66°34.80' W145°12.76' NOTAM FILE FYU.

FAIRBANKS

NDB (HW) 242 FTO at Fort Yukon. 457/20E.

H-1B, L-4J

YUKON RIVER BRIDGE N66°00.55' W149°48.52'

FAIRBANKS

RCD -122.15 (FAIRBANKS FSS)

L-4J