

ANVIK

ANVIK (ANV)(PANV) 1 SE UTC-9(-8DT) N62°38.84' W160°11.40'

297 B NOTAM FILE ANV

RWY 17-35: 4000X75 (GRVL) MIRL

RWY 17: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.

RWY 35: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.

SERVICE: LGT ACTIVATE MIRL Rwy 17-35, PAPI Rwy 17 & 35, REIL Rwy 17 & 35—122.7.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to landing. 77' trees 200' east of windssock may result in erroneous wind indications.

AIRPORT MANAGER: 907-438-2416

WEATHER DATA SOURCES: AWOS-3P 133.55 (907) 663-6353. (WX CAM)

COMMUNICATIONS: CTAF/UNICOM 122.7

RCO 122.4 (KENAI RADIO)


ANCHORAGE CENTER APP/DEP CON 135.7

RADIO AIDS TO NAVIGATION: NOTAM FILE ANV.

NDB (HW) 365 ANV N62°38.49' W160°11.12' at fld.
318/15E.

COMM/NAV/WEATHER REMARKS: For a toll free call Kenai FSS dial 1-866-864-1737.

MC GRATH
H-1B, 2I, L-3C
IAP



ANVIK SPB (K4Ø) 0 NW UTC-9(-8DT) N62°39.37' W160°12.33'

52 NOTAM FILE ANV

WATERWAY E-W: 2000X500 (WATER)

SEAPLANE REMARKS: Unattended. No services or dock. Beaching area on shore near village. Boats park in beaching area. Operating area in Anvik River.

COMMUNICATIONS: CTAF 122.7

RADIO AIDS TO NAVIGATION: NOTAM FILE ANV.

NDB (HW) 365 ANV N62°38.49'
W160°11.12' 313° 1.0 NM to fld. 318/15E.

COMM/NAV/WEATHER REMARKS: For a toll free call Kenai FSS dial 1-866-864-1737.

MC GRATH



313° 1.0 NM From
Anvik "ANV" NDB