


ANVIK**ANVIK** (ANV)(PANV) 1 SE UTC-9(-8DT) N62°38.84' W160°11.40'

297 B NOTAM FILE ANV

RWY 17-35: 4000X75 (GRVL) MIRL**RWY 17:** REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.**RWY 35:** REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.**SERVICE:** LGT ACTIVATE MIRL Rwy 17-35, PAPI Rwy 17 & 35, REIL Rwy 17 & 35—122.7.**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to landing. 77' trees 200' east of windsock may result in erroneous wind indications. Cold temperature restricted airport. Altitude correction required at or below -32C.**AIRPORT MANAGER:** 907-438-2416**WEATHER DATA SOURCES:** AWOS-3P 133.55 (907) 663-6353. (WX CAM)**COMMUNICATIONS:** CTAF/UNICOM 122.7

RCO 122.4 (KENAI RADIO)

ANCHORAGE CENTER APP/DEP CON 135.7

RADIO AIDS TO NAVIGATION: NOTAM FILE ANV.**NDB (HW)** 365 ANV N62°38.49' W160°11.12' at fld. 318/15E.**COMM/NAV/WEATHER REMARKS:** For a toll free call Kenai FSS dial 1-866-864-1737.**MC GRATH**
H-1B, 2I, L-3C
IAP**ANVIK SPB** (K40) 0 NW UTC-9(-8DT) N62°39.37' W160°12.33'

52 NOTAM FILE ANV

WATERWAY E-W: 2000X500 (WATER)**SEAPLANE REMARKS:** Unattended. No services or dock. Beaching area on shore near village. Boats park in beaching area. Operating area in Anvik River.**COMMUNICATIONS:** CTAF 122.7**RADIO AIDS TO NAVIGATION:** NOTAM FILE ANV.**NDB (HW)** 365 ANV N62°38.49'

W160°11.12' 313° 1.0 NM to fld. 318/15E.

COMM/NAV/WEATHER REMARKS: For a toll free call Kenai FSS dial 1-866-864-1737.**MC GRATH**