

PIQUA/HARTZELL FLD (I17) 3 NW UTC-5(-4DT) N40°09.88' W84°18.51'

993 B NOTAM FILE DAY

RWY 08-26: H3998X75 (ASPH) S-30, D-36 MIRL

RWY 08: REIL. PAPI(P2L)—GA 3.0° TCH 36'. Tree.

RWY 26: REIL. PAPI(P2L)—GA 3.0° TCH 37'.

SERVICE: S2 FUEL 100LL, JET A1+ LGT ACTIVATE REIL Rwy 08 and Rwy 26; MIRL Rwy 08-26—CTAF. PAPI Rwy 08 and Rwy 26 opr consly. Rwy 08 PAPI unusbl byd 6° right of enrtln.

AIRPORT REMARKS: Attended Mon-Fri 1300-2200Z†. Unatddd major hols. Fuel avbl H24 via credit card. Arpt conds unmon Mon-Fri 2100-1300Z†, Sat-Sun, and hols. Propeller repairs avbl. Aerobatic box lctd wi 1 NMR of arpt, blw 4500' MSL SR-SS.

AIRPORT MANAGER: 937-778-4207

COMMUNICATIONS: CTAF/UNICOM 123.0

® COLUMBUS APP/DEP CON 118.425

CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

DAYTON (VL) (L) VOR/DME 114.5 DQN Chan 92 N40°00.99' W84°23.81' 026° 9.8 NM to fld. 989/1W.

DME unusable:

Byd 35 NM blo 2,900'

VOR unusable:

245°-250° byd 40 NM

ROSEWOOD (H) (H) VORTACW 117.5 ROD Chan 122 N40°17.27' W84°02.59' 244° 14.3 NM to fld. 1080/5W.

TACAN AZIMUTH unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

PORT BUCYRUS/CRAWFORD CO (See BUCYRUS on page 266)

PORT CLINTON

ERIE-OTTAWA INTL (PCW)(KPCW) 3 E UTC-5(-4DT) N41°30.98' W82°52.17'

590 B LRA NOTAM FILE CLE

RWY 09-27: H5646X100 (ASPH-GRVD) S-100 HIRL

RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Thld dspclcd 201'. Tree.

RWY 18-36: H4002X75 (ASPH) MIRL

SERVICE: S4 FUEL 100LL, JET A+ OX 1, 2, 3, 4 LGT Actvt REIL Rwy 09 & 27; HIRL Rwy 09-27; MIRL Rwy 18-36—CTAF. PAPI Rwy 09 & 27 opr consly.

AIRPORT REMARKS: Attended 1200-2300Z†. Birds and otr wildlife on and invof arpt. Taxilane A clsd to acct with wingspan more than 49'. Rwy 09-27 markings faded. Rwy 09-27 gross wgt: AUW-100. Cstms avbl 24 hrs 7 days per week, req must be made prior to arr, lcl office 419-732-4446. Hngr storage on avbly, aft hrs PPR. Rwy 09-27 calm wind rwy.

AIRPORT MANAGER: 419-734-6297

WEATHER DATA SOURCES: AWOS-3 118.775 (419) 734-9955.

COMMUNICATIONS: CTAF/UNICOM 122.8

® CLEVELAND APP/DEP CON 126.35

CONTINUED ON NEXT PAGE

CONTINUED FROM PRECEDING PAGE

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.

DRYER (VH) (DH) VOR/DME 113.6 DJB Chan 83 N41°21.48' W82°09.72' 292° 33.3 NM to fld. 780/5W.

VOR unusable:

001°-010° byd 40 NM
 020°-024° byd 40 NM
 034°-040° byd 40 NM
 080°-095° byd 40 NM
 110°-120° byd 40 NM
 135°-145° byd 40 NM
 135°-150°
 155°-165°
 160°-165° byd 40 NM
 185°-195° byd 40 NM
 187°-197°
 210°-224° byd 40 NM
 211°-218°
 225°-235° byd 40 NM blo 11,000'
 225°-235° byd 95 NM
 225°-245° byd 20 NM blo 3,500'
 245°-265° byd 40 NM
 275°-285° byd 40 NM blo 18,000'
 286°-355° byd 40 NM

DME unusable:

187°-197°
 289°-310°
 322°-332°
 350°-060°

PORT CLINTON NDB (MHW) 423 PCW N41°31.12' W82°52.13' at fld. 585/7W.

PORTAGE CO (See RAVENNA on page 314)

PORTSMOUTH

GREATER PORTSMOUTH RGNL (PMH)(KPMH) 10 NE UTC-5(-4DT) N38°50.43' W82°50.84'

CINCINNATI

663 B NOTAM FILE DAY

H-10G, L-26G

RWY 18-36: H5001X100 (ASPH) S-30, D-42, 2D-70 MIRL

IAP

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 25'.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 31'.

SERVICE: S4 FUEL 100LL, JET A1+ LGT Actvt REIL Rwy 18 & 36;
 MIRL Rwy 18-36—CTAF. PAPI Rwy 18 & 36 opr consly.

AIRPORT REMARKS: Attended 1400-2200Z†. Hill obstruction lgts
 460' (1124') 1 mile south and 410' (1074') 1/2 mile northwest.
 No line of sight between rwy ends, acft not visible from one rwy end
 to other. Ldg fee for turbine acft waived with fuel purchase, ctc arpt
 for dtls.

AIRPORT MANAGER: 740-820-2700

WEATHER DATA SOURCES: AWOS-3 125.175 (740) 820-2500.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ HUNTINGTON APP/DEP CON 128.4

CLEARANCE DELIVERY PHONE: For CD ctc Huntington ATCT at
 304-453-2490.

RADIO AIDS TO NAVIGATION: NOTAM FILE LOU.

YORK (L) (L) VORTAC 112.8 YRK Chan 75 N38°38.65'
 W82°58.70' 033° 13.3 NM to fld. 1040/5W.

