404 WISCONSIN

## WHITEWATER

**GUTZMER'S TWIN OAKS** (5Y3) 1 NW UTC-6(-5DT) N42°51.21′ W88°45.59′

821 TPA-1621(800) NOTAM FILE GRB

RWY 18-36: 2523X140 (TURF) LIRL(NSTD) 0.8% up S

RWY 36: Tree.

SERVICE: LGT Rwy 18-36 NSTD LIRL, Igts flush mounted.

AIRPORT REMARKS: Attended Apr-Nov 1400Z‡-SS. Rwy 18-36 not plowed winters. Arpt CLOSED to wheeled acft when rwy snow covered. Extensive ultralight and hang glider ops on and invof arpt. Rwy 18-36 not sanded or plowed. Rwy 18 mkd with yellow cones. Rwy 36 dthr mkd with yellow cones.

AIRPORT MANAGER: (920) 723-1556

**COMMUNICATIONS: CTAF 122.9** 

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

WICKR N45°19.08′ W91°48.16′ NOTAM FILE RPD.

**GREEN BAY** 

CHICAGO

NDB (LOMW) 221 RP 010° 6.3 NM to Rice Lake Rgnl/Carl'S Fld. 1215/1E.

WILD ROSE IDLEWILD (W23) 2 NE UTC-6(-5DT) N44°11.87′ W89°13.07′ CHICAGO

908 B NOTAM FILE GRB

RWY 09-27: 2990X100 (TURF) LIRL(NSTD) 0.3% up W

RWY 09: Road. RWY 27: Road

RWY 18-36: 1695X100 (TURF)

RWY 18: Trees.

RWY 36: Trees.

SERVICE: LGT ACTIVATE LIRL Rwy 09-27—CTAF. Rwy 9-27 NSTD thid lgts, do not comply with FAA standard.

AIRPORT REMARKS: Unattended. Rwy 18-36 CLOSED Nov 15 thru Apr 1. Rwy 09-27 plowed winter months. Ultralight activity on and invof arpt. Deer and cranes on and invof arpt. Rwy 18-36 and Rwy 09-27 marked with yellow cones.

AIRPORT MANAGER: 920-420-8443 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.