

LEOTI

MARK HOARD MEML (3K7) 2 S UTC-6(-5DT) N38°27.45' W101°21.05'
 3303 B NOTAM FILE ICT
RWY 17-35: H5100X75 (CONC-NONE) PCN 5 R/C/W/T MIRL
RWY 17: PAPI(P2L)—GA 3.0° TCH 40' .
RWY 35: PAPI(P2L)—GA 3.0° TCH 40' .

RUNWAY DECLARED DISTANCE INFORMATION

RWY 17: TORA-5100 TODA-5100 ASDA-5100 LDA-5100
RWY 35: TORA-5100 TODA-5100 ASDA-5100 LDA-5100

SERVICE: FUEL 100LL **LGT ACTVT** PAPI Rwy 17 and 35, MIRL RWY 17-35—CTAF. Rwy 35 PAPI unusbl byd 8 degs right of cntrln.

AIRPORT REMARKS: Unattended. For fuel call 620-375-2723/4950. 24 hr public avbl 620-375-4649.

AIRPORT MANAGER: 620-874-0432

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **DENVER CENTER APP/DEP CON** 132.7


CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE GCK.

GARDEN CITY (VH) (H) VORTACW 113.3 GCK Chan 80 N37°55.14' W100°43.50' 307° 43.8 NM to fld. 2878/11E.

TACAN AZIMUTH unusable:

280°-010° blo 4,000'
 280°-010° byd 11 NM



WICHITA

L-10G

IAP

LIBERAL MID-AMERICA RGNL (LBL)(KLBL) 2 W UTC-6(-5DT) N37°02.64' W100°57.60'
 2886 B ARFF Index—See Remarks NOTAM FILE LBL
RWY 17-35: H7105X100 (CONC-GRVD) S-80, D-100, 2S-127
 PCN 33 R/D/X/U HIRL

RWY 17: REIL. VASI(V4L)—GA 3.0° TCH 54' .

RWY 35: MALSR. VASI(V4L)—GA 3.0° TCH 57' .

RWY 04-22: H5000X75 (CONC) S-30, D-60 PCN 10 R/D/Y/U MIRL

RWY 04: REIL. PAPI(P4L)—GA 3.0° TCH 40' .

RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 40' .

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-5000 TODA-5000 ASDA-5000 LDA-5000

RWY 17: TORA-7105 TODA-7105 ASDA-7105 LDA-7105

RWY 22: TORA-5000 TODA-5000 ASDA-5000 LDA-5000

RWY 35: TORA-7105 TODA-7105 ASDA-7105 LDA-7105

SERVICE: S4 FUEL 100LL, JET A **OX 2** **LGT** ACTIVATE MIRL Rwy 04-22, and HIRL Rwy 17-35, MALSR Rwy 35, VASI Rwy 17 and Rwy 35, PAPI Rwy 04 and Rwy 22, REIL Rwy 04, Rwy 17 and Rwy 22—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1200-0200Z†, Sat-Sun 1300-0200Z†. 24 hr PPR for unscheduled air carrier ops with more than 30 passenger seats call arpt manager 620-626-2207 or 620-626-0150. Air carrier ops over 9 passenger seats not authorized over 15 minutes before or after scheduled arrival or departure times exc with prior coordination with arpt manager or fire department. Class I, ARFF Index A. ARFF Index B is provided.

AIRPORT MANAGER: (620) 626-0188

WEATHER DATA SOURCES: AWOS-3PT 118.375 (620) 624-1221.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.4 (WICHITA RADIO)

Ⓡ **KANSAS CITY CENTER APP/DEP CON** 134.0

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Kansas City ARTCC at 913-254-8508.

AIRSPACE: CLASS E svc 1200-0300Z†; other times CLASS G.


RADIO AIDS TO NAVIGATION: NOTAM FILE LBL.

(H) (H) VORTACW 112.3 LBL Chan 70 N37°02.66' W100°58.27' at fld. 2891/11E.

TACAN AZIMUTH unusable:
 240°-280°

PANCK NDB (LOM) 383 LB N36°57.87' W100°57.38' 352° 4.8 NM to fld.

ILS 111.3 I-LBL Rwy 35. Class IE. LOM PANCK NDB. Unmonitored.



WICHITA

H-6G, L-15C

IAP, AD