

**LINCOLN MUNI** (ØR2) 0 N UTC-6(-5DT) N38°24.14' W93°19.94'**KANSAS CITY**

940 NOTAM FILE COU

**RWY 18-36:** 2940X125 (TURF)**RWY 18:** Thld dspcd 340'. Trees.**RWY 36:** Thld dspcd 240'. Fence.

**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. +50' treeline 125' west of rwy centerline full length. NSTD rwy safety areas beyond each rwy end, insufficient length, fences, brush, trees and large rwy end markers. Rwy 18-36 soft at thld ends after heavy rain. Rwy 18-36 marked with large yellow cones. Rwy 18 dspcd thld marked with 3 large yellow cones on both sides of rwy. Rwy 18 dspcd thld 7' higher than rwy end elevation; Rwy 36 dspcd thld 4' higher than rwy end elevation.

**AIRPORT MANAGER:** 660-723-3970**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Whiteman Apch at 660-687-3132. When Whiteman Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.

**LINN****STATE TECHNICAL COLLEGE OF MISSOURI** (1H3) 2 SE UTC-6(-5DT) N38°28.30' W91°49.03'**KANSAS CITY**

953 B NOTAM FILE COU

**L-27B****RWY 09-27:** H3400X60 (CONC) S-12.5 MIRL**RWY 09:** REIL. PAPI(P4L)—GA 3.3° TCH 45'.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 37'. Trees.

**SERVICE:** FUEL 100LL LGT MIRL Rwy 09-27 preset on medium ints, to increase ints and ACTIVATE REIL and PAPI Rwy 09 and Rwy 27 and windsock—CTAF. REIL Rwy 27 OTS indef.

**AIRPORT REMARKS:** Attended Mon-Fri irregularly. Fuel self svc 24 hrs. Deer on and invof arpt. Waterfowl on and invof arpt.

**AIRPORT MANAGER:** (573) 897-5000**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Mizzou Apch at 417-868-5620/5619.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE VIH.

**VICHY (L) (L) VORW/DME** 117.7 VIH Chan 124 N38°09.24' W91°42.41' 339° 19.7 NM to fld. 1105/6E.

**LUNNS** N37°12.18' W94°33.51' NOTAM FILE COU.**KANSAS CITY****NDB (LOMW)** 344 JL 132° 4.1 NM to Joplin Rgnl. 914/4E.**M GRAHAM CLARK DOWNTOWN** (See BRANSON on page 224)**MACON-POWER MEML** (K89) 1 SE UTC-6(-5DT) N39°43.79' W92°27.40'**KANSAS CITY**

878 B NOTAM FILE COU

**L-27A****RWY 02-20:** H4150X75 (CONC) S-12.5 MIRL 0.7% up S**IAP**

**RWY 02:** REIL. PAPI(P4L)—GA 3.0° TCH 31'. Thld dspcd 596'. Road. Rgt tfc.

**RWY 20:** REIL. PAPI(P4L)—GA 3.0° TCH 41'.

**SERVICE:** S4 FUEL 100LL, JET A+ LGT ACTIVATE REIL Rwy 02 and 20, PAPI Rwy 02 and Rwy 20, MIRL Rwy 02-20—CTAF. PAPI Rwy 20 unusbl byd 5° left of cntrl.

**AIRPORT REMARKS:** Attended 1400-2300Z. Deer on rwy at early and late hrs. Ultralight activity on and invof arpt. For svc after hrs call 660-385-6208. Self svc 100LL and Jet-A fuel avbl 24 hrs. Crop dusting acct on and invof arpt Apr-Oct.

**AIRPORT MANAGER:** 660-385-6208**COMMUNICATIONS:** CTAF/UNICOM 122.8

® **KANSAS CITY CENTER APP/DEP CON** 125.25

**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE COU.

**(L) DME** 112.9 MCM Chan 76 N39°39.24' W92°28.93' 015° 4.7 NM to fld. 852.

