

ADIRONDACK RGNL (See SARANAC LAKE on page 243)

AIRHAVEN (See STAATSBURG on page 249)

AIRLANE ENTERPRISES (See CLAY on page 195)

AKRON/JESSON FLD (9G3) 1 E UTC-5(-4DT) N43°01.27' W78°28.96'

DETROIT

840 B NOTAM FILE BUF

L-31E

RWY 07-25: H3268X75 (ASPH) S-8 MIRL 0.3% up NE

IAP

RWY 07: PAPI(P2L)—GA 4.0° TCH 54'. Trees.

RWY 25: REIL. PAPI(P2L)—GA 4.0° TCH 55'. Trees.

RWY 11-29: 1955X50 (TURF)

RWY 11: Trees.

RWY 29: Trees.

SERVICE: FUEL 100LL LGT Actvt PAPI Rwy 07 & 25—CTAF. SS-SR, actvt REIL Rwy 25; MIRL Rwy 07-25—CTAF. Rwy 07 VGS1 unusbl byd 7 degs right of cntrln.

NOISE: Rwy 25 noise abatement—maintain rwy holding until 3/4 miles byd dep end Rwy 25 before turning.

AIRPORT REMARKS: Attended Jan-Dec Mon-Sat 1330-2130Z†.

Attendance hrs subject to change. 100LL fuel avbl 24 hrs. Call arpt mgr. Rwy 11-29 CLOSED indefinitely. Parallel twy lighted and 35' wide. Rwy 07 +40' trees 172' right, 263' from rwy, +49' trees 200' - 230' left, 208' - 332' from runway, +34' trees penetrate transition sfc on right side of runway (310' from centerline, 0' - 310' down runway). Rwy 25 +43' trees, 135' left, 454' from runway, + 15' road 300' from rwy, OB.

AIRPORT MANAGER: 716-542-4607

COMMUNICATIONS: CTAF/UNICOM 122.725

Ⓡ **BUFFALO APP/DEP CON** 126.15

CLEARANCE DELIVERY PHONE: For CD etc Cleveland ARTCC at 440-774-0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE BUF.

BUFFALO (DH) DME 116.4 BUF Chan 111 N42°55.74' W78°38.78' 052° 9.1 NM to fld. 730.

DME unusable:

051°-085° byd 25 NM blo 4,500'

301°-050° byd 25 NM blo 3,500'

