226 NEW YORK

CONTINUED FROM PRECEDING PAGE

AIRPORT REMARKS: Special Air Traffic Rules—Part 93 High Density Arpt. Prior reservation rgrd. See Aeronautical Information Manual. Attended continuously. Flocks of birds on and invof arpt. General Aviation, non based coml acft oprs must make arrangements for fuel prior to arr call 347-566-6620 or UNICOM 122.95. Acft opr and twy restrictions exist for A380, B747-800, B777-300ER and A340-600, and A350-1000. Please ctc JFK arpt ops for more info. High volume of low level VFR traffic, 500' and blo, along shoreline south of JFK. Para-sail and banner towing ops 1000' and blo in upper and lower New York bays incl Rockaway Inlet indef. Caution Rwy 13R can be confused with Rwy 13L. Converging ops on Rwy 13R and Rwy 22L conducted via arr distance window. Coded transponder rqrd. Exp to leave and re-enter the Class B Airspace dur moderate to heavy arr periods. ASDE-X in use. Operate transponders with altitude reporting mode and ADS-B (if equipped) enabled on all airport surfaces. Metering procedures in effect-ctc ramp ctl prior to pushback 1200-1500Z‡ daily, 1900-0300Z‡ daily, RLLS Rwy 13L uses 1000' lgt station of the ALS only with CRI VOR apchs and is angled toward AQUEDUCT, also 5 SFL from 1200'-2000' and a 5 SFL grouping aprx 1 mile from rwy +1 adjacent forming apch. Apch gate angled 35° south of Rwy 13L cntrln designed to provide earlier ident of rwy environment. Continuous taxiway maintenance activites at numerous locations. A380 and B747-800 acft tax speed restricted to max 17 kts/20 mph on all twys. Twy A between Twy NA and Twy NB acft speed restriction of 17 kts/20 mph maximum for A380, B747-800, B747-400, B777-300ER, B777-200, A340, A330, B787 and A350. UFN Twy D between Twy C and hangar 7 clsd. Twy H CL lgts between Twy A and Rwy 04L-22R OTS. Twy H CL lgts between terminal 4 ramp and Twy A OTS. Twy NB clsd to Southbound turns at Twy A. Acft are not permitted to stop on either Twy A or B bridges. Twy Z btn Rwy 04L and 22R and Twy Y clsd UFN. Periodic fire department training adjacent apch end of Rwys 22L and 22R. Twy Q3 cntrln lights OTS. Rwy 31R holding position markings at Rwy 04L-22R southeast side obsc. Rwy 13L holding position markings at Rwy 04L-22R northwest side obsc. Obstruction bldg lgt OTS 6.3 NM ESE JFK 222' MSL (220' AGL). NSTD engineered materials Arresting System (EMAS) 393' in length by 226' in width lctd at ther DER 04R. NSTD engineered materials Arresting System (EMAS) 405' in length by 226' in width lctd at ther DER 22L. Rwy status lgts in ops. Rwy 31R 1000 ft dist remaining sign misg. JFK apn bldg 73 ramp clsd to acft wingspan more than 171 ft exc under tow, Non-std markings in general aviation app. ctc FBO on UNICOM or 347-566-6620 for wing walkers. Obst parked acft (ASN 2020-AEA-1302-NRA) 403933N 0734749W (1.4NM NW JFK) 74 (64 ft AGL) U/S 1200-0100 dly. Ldg fee. Flight Notification Service (ADCUS) avbl.

```
AIRPORT MANAGER: (718) 244-3501
 WEATHER DATA SOURCES: ASOS (718) 656-0956 LLWAS. TDWR.
 COMMUNICATIONS: D-ATIS ARR/DEP 128.725 D-ATIS ARR-SW 115.4 D-ATIS ARR-NE 117.7 UNICOM 122.95
   KENNEDY RCO 122.1R 115.9T (NEW YORK RADIO)
® NEW YORK APP CON 125.7 128.125
® NEW YORK DEP CON 135.9
  TOWER 119.1 (Rwys 04R-22L and 13L-31R) 123.9 (Rwy 04L-22R and 13R-31L)
  GND CON 121.9 CLNC DEL/PRE TAXI CLNC 135.05 RAMP CTL 125.05
  CPDLC (LOGON KUSA)
 AIRSPACE: CLASS B See VFR Terminal Area Chart.
 RADIO AIDS TO NAVIGATION: NOTAM FILE JFK.
   KENNEDY (H) (H) VOR/DME 115.9 JFK Chan 106 N40°37.97′ W73°46.28′
                                                                          at fld. 10/12W.
  VOR unusable:
     340°-345° bvd 20 NM blo 4.000°
     340°-345° byd 30 NM
  CANARSIE (T) (T) VÓRW/DME 112.3 CRI Chan 70 N40°36.75′ W73°53.67′ 084° 5.5 NM to fld. 4/11W.
  VOR unusable:
    047^{\circ} - 175^{\circ}
     224°-035°
  ILS/DME 110.9 I-HIQ Chan 46 Rwy 04L. Class IE. Glideslope unusable byd 5° right of course. Auto cpd apchs NA
    blw 500ft MSI.
  ILS/DME 109.5 I-JFK Chan 32 Rwv 04R. Class IIIE. DME also serves Rwv 22R.
  ILS/DME 111.5 I-TLK Chan 52 Rwv 13L. Class IIE. LOC unusable bvd 11 DME, DME unusable bvd 30° right of
    centerline. Glideslope unusable byd 8 NM.
  ILS/DME 110.9 I-IWY Chan 46 Rwv 22L. Class IIIE.
  ILS/DME 109.5 I-JOC Chan 32 Rwy 22R. Localizer offset angle 2.5 deg. DME also serves Rwy 04R.
  ILS 111.35 I-MOH Rwy 31L. Class IE.
```

ILS/DME 111.5 I-RTH Chan 52 Rwy 31R. Class ID. LOC unusable byd 15° left side of course. ILS RTH markings

obsc at Twy K indef.

COMM/NAV/WEATHER REMARKS: Use caution for possible radio interference or false instructions on twr frequencies.