

WEST 30TH ST HELIPORT (JRA)(KJRA) 0 N N40°45.29' W74°00.42'
7 NOTAM FILE ISP

NEW YORK
COPTER

- HELIPAD H1: H45X45 (ASPH) S-6 PERIMETER LGTS
- HELIPAD H1: Rgt tfc.
- HELIPAD H2: H45X45 (ASPH) S-6
- HELIPAD H2: Rgt tfc.
- HELIPAD H3: H45X45 (ASPH)
- HELIPAD H4: H45X45 (ASPH)
- HELIPAD H5: H45X45 (ASPH)
- HELIPAD H6: H45X45 (ASPH)
- SERVICE: FUEL JET A

HELIPORT REMARKS: Attended continuously. North and south finger pier pads are clsd. +40' lgts lctd at south end of heliport. +10' fencing lctd along east edge of heliport and btn ldg spots 2 and 3. All tkfs and ldgs made over Hudson River. Fire alarm box to nearby firehouse lctd at fac. All helipads, H1, H6 circular. Helipad H3 no ingress/egress over 12th Avenue. Parking avbl. Helipad H1 perimeter lgts.

AIRPORT MANAGER: 212-563-4442

COMMUNICATIONS: CTAF/UNICOM 123.05

APP/DEP CON 126.05 127.85

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2849.

NEWFANE

HOLLANDS INTL FLD (85N) 3 SW UTC-5(-4DT) N43°15.29' W78°45.93'
360 NOTAM FILE BUF

DETROIT

- RWY NE-SW: 2875X75 (TURF)
- RWY NE: Trees.
- RWY SW: Trees.

AIRPORT REMARKS: Unattended. Parachute Jumping. Rwy SW nmrs 100' trees srnd rwy. Rwy NE; nmrs trees +25'--80' tall; 50' left to 143' right of cntrln. Rwy NE/SW Rolling terrain. 4" ditch between rwy and txy. Rwy used for farming. Large round hay bales on rwy; unsafe for acft.

AIRPORT MANAGER: 716-536-8653

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0490.