CARLISLE (N94) 2 SE UTC-5(-4DT) N40°11.27′ W77°10.46′ 510 B NOTAM FILE IPT

DETROIT L-29E, A IAP

RWY 10-28: H4008X60 (ASPH) S-12.5, D-12.5 LIRL

RWY 10: Tree

RWY 28: Thid dsplcd 126'. Tree.

SERVICE: S2 FUEL 100LL, JET A+ LGT ACTVT LIRL Rwy 10–28—CTAF.

AIRPORT REMARKS: Attended Mon–Fri 1400–2200Z‡. Nov 15–Mar 1 Sat–Sun unattended. Mar 2–Nov 14 Sat–Sun 1400–2100Z‡. During ngt ops trailer park Igts located south of rwy could be mistaken for rwy Igts. Deer and birds on and invof arpt. Lrg bird act increased .5 NM W apch end Rwy 10.

AIRPORT MANAGER: 717-448-7730
COMMUNICATIONS: CTAF/UNICOM 122.8

B HARRISBURG APP/DEP CON 124.1

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.
RADIO AIDS TO NAVIGATION: NOTAM FILE CXY.


HARRISBURG (L) (L) VORTACW 115.35 HAR Chan 100(Y) N40°18.13´W77°04.17´ 225° 8.4 NM to fld. 1301/10W.

VOR unusable: 097°-107° byd 10 NM

146°-168° byd 20 NM blo 7,000′

CASTLE N41°01.38′ W80°24.95′ NOTAM FILE AOO.

NDB (MHW) 272 UCP at New Castle Muni. 1023/9W.



DETROIT L-30H

CENTRE AIRPARK (See CENTRE HALL on page 267)

CENTRE HALL

CENTRE AIRPARK (N16) 2 SE UTC-5(-4DT) N40°48.70′ W77°39.43′

DETROIT

DETROIT

1307 NOTAM FILE AOO RWY 06-24: 3100X210 (TURF)

RWY 06: Thid dsplcd 400'. Road.

RWY 24: Thid dsplcd 400'. Trees.

AIRPORT REMARKS: Attended irregularly. For svc after hrs call 570–419–7509. Ultralight activity on and invof arpt. RC airplane ops on invof arpt. Rwy 06–24 not maintained winter months. Rwy 06 thld unmarked. Rwy dsplc thld marked at 700′. Rwy 24 thld unmarked. Rwy 24 dsplcd thld marked at 650′.

AIRPORT MANAGER: (814) 364-9188 COMMUNICATIONS: CTAF/UNICOM 122.7

CLEARANCE DELIVERY PHONE: For CD ctc New York ARTCC at 631-468-1425.

PENNS CAVE (N74) 4 NE UTC-5(-4DT) N40°53.40′ W77°36.19′

1245 NOTAM FILE AOO

RWY 07-25: H2509X40 (ASPH) 0.9% up NE

RWY 07: Tree.

AIRPORT REMARKS: Attended irregularly. For svc call (814) 364–1479. Deer on and invof arpt at ngt. 750′ AGL mountains 1/2 mile south and 700′ AGL mountain 1/2 mile north, both unlgtd and unmarked. Rwy 07–25 first 864′ of Rwy 07 has a 3.3% upslope. No ngt ops.

AIRPORT MANAGER: 814-364-1479 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York ARTCC at 631-468-1425.