

ELKTON

CLAREMONT (58M) 3 SW UTC-5(-4DT) N39°34.45' W75°52.19'
106 B NOTAM FILE DCA

RWY 13-31: H2989X70 (ASPH-AFSC) MIRL 1.5% up NW

RWY 13: REIL. PAPI(P2R)—GA 5.0° TCH 6'. Thld dspcd 288'. Trees.

RWY 31: REIL. PAPI(P2L)—GA 4.0° TCH 6'. Thld dspcd 601'. Trees.

SERVICE: S2 **FUEL** 100LL **LGT** Actvt rotg bcn—123.0. Actvt REIL Rwy 13 & 31; PAPI Rwy 13 & Rwy 31; MIRL Rwy 13-31—123.0.

AIRPORT REMARKS: Attended 1400-2100Z. Deer and birds on and invof arpt. Reduced braking action Rwy 13 downhill 1.5 deg. Calm/light wind use Rwy 31. Fuel: 100LL self serve. Rwy 13-31 no TGL. Rwy 13-31 unfilled cracks, alligator cracking, lateral and longl cracking, veg growth, oxidation. Rwy 13 and 31 markings faded.

AIRPORT MANAGER: (410) 398-0234

COMMUNICATIONS: CTAF/UNICOM 122.8

® **PHILADELPHIA APP/DEP CON** 118.35

CLEARANCE DELIVERY PHONE: For CD ctc Philadelphia Apch at (800) 354-9884.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

SMYRNA (L) (L) VORTACW 111.4 ENO Chan 51 N39°13.90' W75°30.96' 330° 26.3 NM to fld. 15/9W.

TACAN AZIMUTH unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'


VOR unusable:

159°-169° blo 3,000 . 325-335 byd 15NM blo 4,900'

DME unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'



WASHINGTON

L-34G, A

IAP

ELLICOTT N39°17.24' W76°46.62' NOTAM FILE BWI.

NDB (MHW) 371 **FND** 154° 8.4 NM to Baltimore/Washington Intl Thurgood Marshall. 381/11W.

NDB unusable:

140°-320° byd 12 NM blo 10,500'

WASHINGTON

COPTER

L-29E, 34F, 36I, A

ESSEX SKYPARK (See BALTIMORE on page 92)

FALLSTON (W42) 1 S UTC-5(-4DT) N39°30.08' W76°24.68'

460 NOTAM FILE DCA

RWY 04-22: H2200X50 (ASPH) S-12 LIRL(NSTD)

RWY 04: Thld dspcd 315'. Trees.

RWY 22: Thld dspcd 230'. Trees.

SERVICE: **FUEL** 100LL **LGT** For NSTD LIRL Rwy 04-22 ctc arpt manager 410-877-9889.

AIRPORT REMARKS: Unattended. Arpt CLOSED dusk-1400Z. Arpt unattended major holidays. If attendant not present during dalyt hrs call 410-877-9889. For fuel, if no one present during dalgt hrs call 410-877-9889. Deer and wildlife on and invof arpt. Rwy 04-22 cracking, FOD poss. Rwy 04-22 NSTD LIRL only one thld lgt each side. NSTD LIRL avbl to based acft with prior notice.

AIRPORT MANAGER: 410-877-9889

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-429-5882.

WASHINGTON

COPTER