

**BEAVER MARSH** (2S2) 1 SW UTC-8(-7DT) N43°07.65' W121°48.52'

KLAMATH FALLS

4638 B NOTAM FILE MMV

RWY 18-36: 4500X60 (DIRT) LIRL

RWY 18: Trees.

RWY 36: Trees.

**AIRPORT REMARKS:** Unattended. Clsd winter months exc to ski equipped acft. Rwy 18-36 25' rwy width usable in center. Rwy 18-36 dirt sfc loose and powdery, creates clouds of dust, loose 2-5" rocks on sfc, rough. Numerous patches of 1' brush on rwy. 10-20' trees within 50' of east edge of rwy. Rwy 18-36 1-2 ft trees and shrubs.

**AIRPORT MANAGER:** (541) 554-6143**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**BEND MUNI** (BDN)(KBDN) 5 NE UTC-8(-7DT) N44°05.67' W121°12.01'

KLAMATH FALLS

3459 B TPA—See Remarks NOTAM FILE MMV

H-1B, L-13A

RWY 16-34: H5201X75 (ASPH) S-30 MIRL 1.1% up S

IAF

RWY 16: REIL. PAPI(P4L)—GA 3.0° TCH 38'. Trees. Rgt tfc.

RWY 34: REIL. PAPI(P4L)—GA 3.0° TCH 44'. Tree.

**SERVICE:** S4 FUEL 100LL, JET A OX 1, 3, 4 LGT ACTIVATE REIL Rwy 16 and Rwy 34; PAPI Rwy 16 and Rwy 34; MIRL Rwy 16-34—CTAF.

**NOISE:** NS ABTMT procedures in effect, call FBO at 541-388-0019.**AIRPORT REMARKS:** Attended Mon-Fri 1530-0200Z, Sat-Sun

1600-0100Z. Be aware, intense helicopter training continually in progress. Glider opr on and invof arpt. Extv geese act reported on and near arpt year around, deer and other wildlife may be present. Calm wind rwy is Rwy 16. To avoid property damage exercise judgement and courtesy during run-up invof hangars. Apron areas may be heavily congested at times with svc vehicles, pedestrian and automobile tfc. Taxilanes and apron are NSTD, acft may rqr wing walkers, parking guidance and/or tugging at pilot discretion to insure acft clnc from obstacles. Both twys parallel to Rwy 16-34 marked by reflectors. TPA-rgt pat fixed wing to remain west of rwy using rgt pat Rwy 16 and left pat Rwy 34. Rotor wing to remain east of rwy and use rgt pat 34 and left pat 16. Fixed wing acft—no turns before end of rwy. Segmented circle located at northeast end or arpt. See Special Notices — Intensive Flight Training Advisory

**AIRPORT MANAGER:** 541-647-0828**WEATHER DATA SOURCES:** AWOS-3 134.425 (541) 382-1477.**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDM.

**DESCHUTES (VH) (H) VORTACW** 117.6 DSD Chan 123 N44°15.17' W121°18.21' 137° 10.5 NM to fld.  
4103/18E.

VOR unusable:

013°-023° byd 40 NM

034°-039° byd 40 NM

108°-119° byd 40 NM

125°-135° byd 40 NM

150°-163° byd 40 NM

188°-201° byd 40 NM blo 10,500'

188°-201° byd 69 NM

202°-219° byd 40 NM

220°-240° byd 30 NM

241°-252° byd 40 NM blo 13,000'

241°-252° byd 47 NM

253°-257° byd 40 NM

258°-268° byd 40 NM blo 10,000'

258°-268° byd 48 NM

280°-286° byd 40 NM

289°-305° byd 40 NM blo 12,500'

289°-305° byd 48 NM

326°-338° byd 40 NM

TACAN AZIMUTH unusable:

220°-240° byd 30 NM

DME unusable:

220°-240° byd 30 NM

