

CLEARWATER

TOKETEETEE STATE (3S6) 2 S UTC-8(-7DT) N43°13.41' W122°25.27'

KLAMATH FALLS

3361 NOTAM FILE MMV

RWY 11-29: 5350X60 (TURF) 2.4% up SE

RWY 11: Trees.

RWY 29: Trees.

AIRPORT REMARKS: Unattended. Arpt CLOSED from 1 Nov-1 May. Elk, deer and turkey on and invof arpt. Arpt on West side of Cascades and affected by wx West. Best info on arpt thru US Forest svc Roseburg, or lcl FBO at Roseburg. Rwy 11-29 graded, 60' wide, shoulders rough and rutted. Rwy 11-29 has +120' trees 250' either side of centerline. Rwy 11-29 thlds outlined with white tires. Trees 4'-30' along south side of rwy within 50' of centerline. Sfc conds not rptd.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

COLUMBIA GORGE RGNL/THE DALLES MUNI (See THE DALLES on page 215)

COLUMBIA N45°35.32' W122°36.68' NOTAM FILE PDX.

SEATTLE

(H) **TACAN** 109.2 CBU Chan 29 at Portland Intl. 22/15E.

H-1B, L-1C

TACAN unusable:

025°-035° byd 30 NM blo 9,500'

035°-055° byd 20 NM blo 9,500'

105°-145° byd 65 NM blo 18,000'

125°-135° byd 15 NM blo 8,500'

160°-255° byd 15 NM blo 10,500'

255°-275° byd 20 NM blo 8,500'

DME unusable:

025°-035° byd 30 NM blo 9,500'

035°-055° byd 20 NM blo 9,500'

105°-145° byd 65 NM blo 18,000'

125°-135° byd 15 NM blo 8,500'

160°-255° byd 15 NM blo 10,500'

255°-275° byd 20 NM blo 8,500'

CONDON STATE PAULING FLD (3S9) 1 NE UTC-8(-7DT) N45°14.79' W120°09.99'

SEATTLE

2911 B NOTAM FILE MMV

L-13A

RWY 07-25: H3500X60 (CONC) S-12 MIRL

RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Road.

RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: LGT ACTIVATE REIL Rwy 07 and Rwy 25; MIRL Rwy 07-25, PAPI Rwy 07 and Rwy 25—CTAF.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Heavy AG ops Feb-Jun.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE DLS.

KLICKITAT (VH) (DH) VORW/DME 112.3 LTJ Chan 70 N45°42.82' W121°06.05' 104° 48.4 NM to fld. 3220/21E.


VOR unusable:

003°-017° byd 40 NM

192°-198° byd 40 NM

207°-211° byd 40 NM

306°-311° byd 40 NM



CORNELIUS

SKYPORT (4S4) 3 N UTC-8(-7DT) N45°34.96' W123°03.17'

SEATTLE

174 NOTAM FILE MMV

RWY 16-34: 2000X45 (TURF)

RWY 16: Trees. Rgt tfc.

RWY 34: Thld dsplcd 200'. Road.

AIRPORT REMARKS: Attended 1400-0400Z. Helicopter and ultralight ops prohibited. Rwy 16-34 rwy ends marked with half barrels. Rwy 34 dsplcd thld marked with L-shaped boards.

AIRPORT MANAGER: 503-648-9311

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 503-493-7545.