274 WASHINGTON

## **STARBUCK**

**LITTLE GOOSE LOCK AND DAM** (16W) 7 NE UTC-8(-7DT) N46°35.04′ W118°00.22′

SEATTLE

681 NOTAM FILE SEA RWY 07-25: 3400X50 (GRVL)

RWY 07: Road. RWY 25: Hill.

AIRPORT REMARKS: Unattended. Do not land if snow present on rwy. No winter snow removal ops. Ctc WA State Aviation Division 360–709–8015 or 1–800–552–0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800–258–5990. Arpt lctd in canyon, rolling terrain 700–800' south rising to 750', canyon wall 800' south rises steeply to 1800'+, north wall rises to 1600'+. Ck density titude. High terrain surrounds arpt. Strong winds possible inside canyon. Pedestrians, vehicles, and animals on and involf rwy. Portions of rwy sfc rough and soft. Grvl does not compact well. Rwy marked with reflectors dur dates arpt is open.

AIRPORT MANAGER: (360) 618-2477 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

STEHEKIN STATE (6S9) 3 NW UTC-8(-7DT) N48°20.75′ W120°43.25′

SEATTLE

1230 NOTAM FILE SEA

RWY 13-31: 2630X100 (TURF) 1.5% up NW

RWY 13: Trees.

AIRPORT REMARKS: Unattended. Arpt CLSD 1 Oct-1 Jun, exc pub safety/law enforcement hops. No mil use exc emerg. Vehicles, pedestrians, and animals on and invof rwy. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Rwy marked with reflectors dur dates arpt is open. High terrain in both approaches close in. Tall trees in both approaches. Strong, gusty winds in canyon. NW end bare gnd. Caution-density altitude. Pilots bring own ropes.

AIRPORT MANAGER: (360) 618-2477 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

STROM FLD (See MORTON on page 245)

SULLIVAN LAKE STATE (See METALINE FALLS on page 245)