

**YAP ISLAND****YAP INTL** (T11)(PTYA) 0 SW UTC+10 N9°29.93' E138°04.95'**P-1A**

91 B AOE NOTAM FILE HNL

**IAP****RWY 07-25:** H6000X150 (ASPH-GRVD) S-75, D-160, 2D-230 MIRL**RWY 07:** REIL. PAPI(P4L)—GA 3.0° TCH 47'. Ground.**RWY 25:** REIL. PAPI(P4L)—GA 3.0° TCH 49'. Ground.**SERVICE: FUEL** JET A1 **LGT** ACTVT REILs 07 and 25; PAPI Rwy 07 and 25; MIRL Rwy 07-25 – 123.6. Bcn OTS.**AIRPORT REMARKS:** Attended Mon–Fri 1730–0230Z, Sat on call, Sun on call. Sat 24 hrs PPR with filed Flt plan or phone (691) 350–2128 Fax (691) 350–2344. PPR for ldg to be filed 48 hrs in advance with the Secretary of Transportation, Federated States of Micronesia, P.O. Box PS-2, Pohnpei, FSM 96941, phone (011)(691) 320–2865. Please see FSM DOTC&I: div. of civil aviation's website for procedures and forms used to request PPR into FSM;

HTTP://WWW.TCI.GOV.FM/CIVILAVIATION/FORMS.HTML. Be alert when taxiing, cracks on right and left side of twy.

Landing fee. Transient acft must make prior arrangements for fuel with Mobil Oil Guam, expect delay.

**AIRPORT MANAGER:** (691) 350–2128**COMMUNICATIONS: CTAF** 123.6**YAP RADIO** 123.6 LAA. 5205X USB emerg only, 2182 emerg only.**RADIO AIDS TO NAVIGATION:****YAP NDB/DME (HW/DME)** 317 YP Chan 122 N09°29.97' E138°05.31' at fld. 80/1E.

DME unusable:

001°–009° byd 10 NM

010°–035° byd 10 NM blo 12,000'

035°–075° byd 25 NM blo 4,000'

076°–105° byd 25 NM

280°–000° byd 25 NM blo 12,000'

**COMM/NAV/WEATHER REMARKS:** Chan 122 paired with VHF freq 117.5.