

<b>DYESS AAF</b> (ROI)(PKRO) UTC+12 N09°23.81' E167°28.25'				P-1B
14	B			IAP
RWY 04-22: H4499X150 (ASPH) PCN 11 F/B/W/T				
RWY 04: PAPI(P4L)—GA 3.0° TCH 38'.				
RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 38'.				
<b>AIRPORT REMARKS:</b> No facilities—ARFF available. No transient acft authorized. Electromagnetic radiation will exist 24 hrs daily within 10 NM radius of Dyess AAF from surface to 50,000. Acft within the abv airspace will be exposed to direct radiation which may produce harmful effect to persons and equipment. REIL available Rwy 04 with prior notice. Five lighted antennae; 263 dish located 0.6 NM E, 175 dish located 0.7 NM ENE, 273 located 1.3 NM SE. 150 located 800S, 210 located 0.4 NM NNW. Military rotating beacon atop 137 ft water tower 950 ft SE. Taxiway unlgtd. NOTE: See Area Notices—MARSHALL ISLANDS.				
<b>COMMUNICATIONS:</b> CTAF 122.9				
SAN FRANCISCO ARINC (HNL) NOTAM FILE HNL.				
ROI RADIO 118.1				
<b>COMM/NAV/WEATHER REMARKS:</b> All acft within 100 NM main twr etc. Bucholz Twr—Opr 2200-0600Z Tue-Sat excld fed hol.				

MAJURO ATOLL

<b>MAJURO</b> N07°03.92' E171°16.12' NOTAM FILE HNL				P-1B
NDB/DME (HW/DME) 316 MAJ Chan 114 at Marshall Islands Intl. 7/10E. DME Chan 114 paired with VHF freq 116.7				
<hr/>				
<b>AMATA KABUA INTL</b> (MAJ)(PKMJ) 7 SW UTC+12 N07°03.90' E171°16.32'				P-1B
7	B			IAP
NOTAM FILE HNL				
RWY 07-25: H7913X150 (ASPH-GRVD) S-120, D-171, 2D-290 PCN 64 F/B/X/T MIRL				
RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 55'.				
RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 45'. Tree.				
<b>SERVICE: FUEL</b> JET A1+ LGT ACTIVATE MIRL Rwy 07-25, PAPI and REIL Rwys 07 and 25—CTAF.				
<b>AIRPORT REMARKS:</b> Attended on request. PPR for ldg from arpt mgr 24 hrs in advance. After sender has confirmed fuel delivery, he must give 24 hours advance notice to Airport Superintendent and Immigration Officer, Majuro, Marshall Islands. If ETA is between 0400Z Fri to 2200Z Mon, 48 hours advance notice must be given to Airport Superintendent. Message will include name of sender, type of aircraft, aircraft identification number, ETA purpose of landing, such as ferry flight, number of crew, PAX and citizenships, and that sender has obtained fuel confirmation from MOBILE OIL Guam including quantity and type of fuel. Include RON in message if applicable. Arpt Superintendent available Sun-Fri 2000-0500Z phone (692) 247-7612/3113, Fax (692) 247-3888.				
<b>AIRPORT MANAGER:</b> (692) 247-3113				
<b>COMMUNICATIONS:</b> CTAF 123.6				
MAJURO RADIO 123.6 LAA 126.6 emerg only 5205X USB emerg only 2182 emerg only.				
<b>RADIO AIDS TO NAVIGATION:</b>				
MAJURO NDB/DME (HW/DME) 316 MAJ Chan 114 N07°03.92' E171°16.12' at fld. 7/10E. DME Channel 114 paired with VHF freq 116.7.				

MEJIT ATOLL

<b>MEJIT</b> (C3Ø) 0 NE UTC+12 N10°17.00' E170°53.00'			
5			NOTAM FILE HNL Not insp.
RWY 07-25: 3000X50 (GRVL-CORAL)			
<b>AIRPORT REMARKS:</b> Attended on call.			
<b>AIRPORT MANAGER:</b> (692) 625-6179			
<b>COMMUNICATIONS:</b> CTAF 122.9			