MIDWAY ATOLL

IDWAY ATOLL HENDERSON FLD (MDY)(PMDY) P 0 SW UTC-11 N28	8°12.09′ W177°22.88′	P-11
12 B Class IV, ARFF Index A NOTAM FILE MDY		IAI
RWY 06-24: H7800X150 (ASPH) S-120, D-230, 2D-430 PC	N 56 F/A/W/U MIRL	
RWY 06: REIL. PAPI(P4L)-GA 3.0° TCH 80'.		
RWY 24: REIL. PAPI(P4L)-GA 3.0° TCH 80'.		
RUNWAY DECLARED DISTANCE INFORMATION		
RWY 06: TORA-7800 TODA-7800 ASDA-7800 LDA-78	00	
RWY 24: TORA-7800 TODA-7800 ASDA-7400 LDA-74	00	
SERVICE: LGT ACTVT REIL Rwy 06 and 24; PAPI Rwy 06 and 24;	; MIRL Rwy 06-24-126.	2.
AIRPORT REMARKS: Attended 1900-0400Z. Use freq 126.2 for all in	nbound and outbound com-	munications. Arpt clsd to all tran
acft. Arpt open for ETOPS and approved acft ops only. Approve	ed acft opns permitted only	during hrs of darkness Nov-Jun
due to heavy bird activity. PPR for ldg for approved acft opns	from arpt manager 24 hrs	in advance due to heavy bird
activity call 808–954-4829. Be alert for heavy bird strike haz	zards at all times. Current l	pird activity status avbl during
initial ctc inbound and prior to tkf and ldg on freq 126.2. Exc	ept when necessary for tkf	and Indg, all acft maintain
minimum alt of 5,000 MSL within 12 miles of arpt. Arpt pri of	ctc (808) 674–1237. Back	kup contact sat phone Arpt
Manager 011-8816-327-20578, USFWS Refuge Manager 0	11-8816-327-33725, DB	SI Manager
001-8816-327-33825. Emergency pager 24 hrs (480) 768-	-2500 ID 881631492770). Landing fee.
AIRPORT MANAGER: (808) 954-4829		
WEATHER DATA SOURCES: AWOS-3P 118.325 (808) 674-9286.		
COMMUNICATIONS: CTAF 122.9		
AIRSPACE: CLASS E SVC		
RADIO AIDS TO NAVIGATION: NOTAM FILE MDY.		
MIDWAY NDB (HW) 400 MDY N28°12.25' W177°22.75'	at fld. 16/10E.	
COMM/NAV/WEATHER REMARKS: No ATCT ops. Inbound acft ctc 100 I	NM out for advisories. CTA	F not monitored ctc freg 126.2.
Freq 126.2 monitored 1900–0400Z and during approved act	ft ops. Arpt advisory on 12	6.2/257.8; 121.5/243.0 avbl.
MIDWAY N28°12.25′ W177°22.75′ NOTAM FILE MDY		P-11