

DECATUR MUNI (LUD)(KLUD) 2 N UTC-6(-5DT) N33°15.26' W97°34.83'

1047 B NOTAM FILE LUD

RWY 17-35: H4200X60 (ASPH) S-12.5, D-17 MIRL

RWY 17: REIL. PAPI(P2L)—GA 3.5° TCH 23'. Tree.

RWY 35: PAPI(P2L)—GA 3.5° TCH 40'. Trees. Rgt tfc.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** Dusk-Dawn. MIRL Rwy 17-35 preset low intst; to incr intst actvt—CTAF.

AIRPORT REMARKS: Attended 1400-2300Z. Deer and wildlife on and invof arpt. Gnd drops sharply 160' north of Rwy 17 thr. Rwy 17-35 extensive pavement cracking. Due to rwy elev chg, acft not vsb at opposite end.

AIRPORT MANAGER: 940-627-2855

WEATHER DATA SOURCES: AWOS-3 118.225 (940) 627-2365.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **REGIONAL APP/DEP CON** 118.1

CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.


BOWIE (H) (H) VORTACW 117.15 UKW Chan 118(Y) N33°32.15' W97°49.28' 138° 20.8 NM to fld. 1102/6E.

DALLAS-FT WORTH

COPTER

L-17C, A

IAP



HERITAGE CREEK AIRSTRIP (58T) 9 SE UTC-6(-5DT) N33°09.96' W97°28.79'

833 NOTAM FILE FTW

RWY 13-31: 3000X60 (TURF) LIRL 0.8% up NW

RWY 13: Tree.

RWY 31: Tree. Rgt tfc.

SERVICE: S4 **LGT** ACTVT LIRL Rwy 13-31 —CTAF. Rwy defined by white "L" markers on each corner—nights: two lights each side of cntrln mark rwy ends.

AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. Parachute activity invof arpt. Remote controlled acft ops on arpt. All acft monitor CTAF due to the close proximity of Rhome Meadows arpt. Rwy 31 right tfc for fixed wing acft only; remain east of the rwy.

AIRPORT MANAGER: (817) 988-9745

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

DALLAS-FT WORTH

COPTER

LAZY G BAR RANCH (Ø9T) 5 NE UTC-6(-5DT) N33°16.88' W97°29.80'

931 NOTAM FILE FTW

RWY 17-35: 1600X40 (TURF-DIRT)

RWY 17: Brush. Rgt tfc.

AIRPORT REMARKS: Unattended. Livestock on and invof arpt. For fld condition call arpt manager. Call ahead to confirm rwy is clear of livestock. Rough, rolling gradient. Full rwy not visible from ends. Center 20' mowed.

AIRPORT MANAGER: (719) 221-7993

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

DALLAS-FT WORTH

TRIPLE-ACE FLD (35X) 2 NE UTC-6(-5DT) N33°15.11' W97°33.21'

1010 NOTAM FILE 35X Not insp.

RWY 02-20: 1271X40 (TURF)

RWY 02: Rgt tfc.

AIRPORT REMARKS: Unattended. Acft oprg into or out of arpt will use Decatur Arpt freq 122.8 to communicate with Decatur Arpt tfc.

AIRPORT MANAGER: 940-627-6800

COMMUNICATIONS: CTAF 122.8

DALLAS-FT WORTH