

**MARINA MUNI** (OAR)(KOAR) 2 NE UTC-8(-7DT) N36°40.89' W121°45.70' **SAN FRANCISCO**  
 137 B NOTAM FILE OAK **L-3B**  
**RWY 11-29:** H3483X75 (ASPH) S-20, D-50 MIRL **IAP**  
**RWY 29:** PAPI(P2L)—GA 3.0° TCH 45'. Rgt tfc.  
**SERVICE:** S4 FUEL 100LL, JET A OX 3, 4 LGT ACTIVATE MIRL Rwy 11-29—CTAF 7 clicks.  
**AIRPORT REMARKS:** Attended Mon-Fri 1600-0100Z±. Fuel avbl (100LL and Jet A) 24 hrs via credit card lock system.  
 Parachute Jumping. Ultralight and skydiving activity on and in/ovf arpt. Skydiving activity on SE side of arpt. Rwy 29 calm wind rwy. 500' stopway departure end Rwy 29. Depart Rwy 29 execute 45° rgt turn to avoid overflight of noise sensitive residential area.  
**AIRPORT MANAGER:** (831) 241-8628  
**WEATHER DATA SOURCES:** AWOS-3PT 134.025 (831) 384-2967.  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
 (R) **NORCAL APP/DEP CON** 133.0 (360°-150°)  
**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-3748.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE SNS.  
**SALINAS (H) VORTACW** 117.3 SNS Chan 120 N36°39.83' W121°36.19' 261° 7.7 NM to fld. 80/17E. **HIWAS.**  
 VOR portion unusable:  
 010°-016° byd 22 NM blo 7,000'  
 010°-016° byd 26 NM blo 8,000'  
 016°-080° byd 22 NM blo 8,000'  
 150°-170° byd 8 NM blo 10,000'  
 TACAN AZIMUTH & DME unusable:  
 010°-080° byd 22 NM blo 8,000'  
 150°-200° blo 11,000'  
 aerobatic acft wi an area defined as .5 NM rds of SNS 357016.4 (5.3 NM w CVH), blo 3000', avoidance advised SR-SS  
 TACAN AZIMUTH unusable:  
 245°-255° byd 20 NM

**MARIPOSA-YOSEMITE** (MPI)(KMPI) 4 W UTC-8(-7DT) N37°30.65' W120°02.37' **SAN FRANCISCO**  
 2254 B NOTAM FILE RIU **L-3B, 9A**  
**RWY 08-26:** H3305X60 (ASPH) S-12 MIRL 0.9% up W **IAP**  
**RWY 08:** PAPI(P2L)—GA 4.0° TCH 36'. Tree. Rgt tfc.  
**RWY 26:** PAPI(P2L)—GA 4.5° TCH 40'. Tree.  
**SERVICE:** S2 FUEL 100LL, JET A LGT ACTIVATE PAPI Rwy 08 and Rwy 26; MIRL Rwy 08-26—CTAF.  
**AIRPORT REMARKS:** Attended Mon-Fri 1800-0000Z±, Sat-Sun 1800-2200Z±. Fuel avbl 24 hrs with credit card. Birds on and in/ovf arpt. Rwy 08 terrain drops along both sides of twy 45' from rwy edge. Limited parking weekends and holidays.  
**AIRPORT MANAGER:** (209) 966-2143  
**WEATHER DATA SOURCES:** AWOS-3 135.6 (209) 966-2912.  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
 (R) **OAKLAND CENTER APP/DEP CON** 121.25  
**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE RIU.  
**FRIANT (L) VORTACW** 115.6 FRA Chan 103 N37°06.27' W119°35.73' 302° 32.3 NM to fld. 2380/17E. **HIWAS.**

## MARKLEEVILLE

**ALPINE CO** (M45) 3 N UTC-8(-7DT) N38°44.09' W119°46.02' **SAN FRANCISCO**  
 5872 TPA-6672(800) NOTAM FILE RNO **L-9A**  
**RWY 17-35:** H4443X50 (ASPH) 1.0% up S  
**RWY 17:** Hill.  
**RWY 35:** Rgt tfc.  
**AIRPORT REMARKS:** Unattended. No snow removal, arpt CLOSED when snow on rwy. Soil conditions off rwy is poor in wet conditions. Call public works for additional information 530-694-2140 extension 0. Large stones along edge of rwy off graded surface. Rwy 17-35 ltd by arpt opr to 4,800 lbs single wheel, 9,600 lbs dual wheel.  
**AIRPORT MANAGER:** 530-694-2140  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE RNO.  
**MUSTANG (H) VORTACW** 117.9 FMG Chan 126 N39°31.88' W119°39.36' 170° 48.0 NM to fld. 5950/16E.  
 VORTAC unusable:  
 200°-230° byd 30 NM blo 13,000'