

MONTAGUE

MONTAGUE—YREKA ROHRER FLD (105) 1 W UTC-8(-7DT) N41°43.80' W122°32.67'

KLAMATH FALLS
L-21

2527 TPA—3327(800) NOTAM FILE RIU

RWY 15-33: H3360X50 (ASPH) S-12 MIRL

RWY 15: Rgt tfc.

RWY 33: VASI(V2L)—GA 3.0° TCH 25'. Thld dsplcd 150'. Road.

RWY 05-23: 2080X100 (TURF)

RWY 23: Rgt tfc.

SERVICE: S2 **FUEL** 100LL **LGT** MIRL Rwy 15-33 preset low ints; to increase ints **ACTIVATE**—CTAF.

AIRPORT REMARKS: Unattended. Deer on and invof arpt. Occasional glider and balloon launches. Be alert to mountain north and hills east and west of arpt. Arpt rstd to acft with maximum certificated tkf weight of 12,500 lbs or less; for more information call arpt ops 530-459-5204. Use of rwy tfc patterns strongly recommended. Avoid overflight of town 1/2 mile east of arpt. Rwy 05-23 edges marked with white tires.

AIRPORT MANAGER: (530) 459-3392

COMMUNICATIONS: CTAF/UNICOM 122.8

ANTELOPE MOUNTAIN RCO 122.4 (RANCHO MURIETA RADIO)

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.

FORT JONES (L) VOR/DME 109.6 FJS Chan 33 N41°26.98' W122°48.39' 016° 20.5 NM to fld. 4900/19E.

HIWAS.

VOR unusable:

080°-135° byd 19 NM

080°-135° byd 9 NM blo 13,000'

190°-300° byd 19 NM

200°-300° byd 8 NM blo 14,000'

DME unusable:

190°-275° byd 19 NM blo 16,000'

NDB (MHW) 404 MOG N41°43.64' W122°28.90' 258° 2.8 NM to fld. 2629/15E. NOTAM FILE SIY. NDB

unmonitored.

NDB unusable:

190°-200° byd 10 NM

SISKIYOU CO (SIY)(KSIY) 3 NE UTC-8(-7DT) N41°46.89' W122°28.09'

KLAMATH FALLS
H-3B, L-21
IAF

2651 B NOTAM FILE SIY

RWY 17-35: H7490X150 (ASPH) S-60, D-180, 2S-175, 2D-270

MIRL

RWY 17: REIL. PAPI(P2L)—GA 3.0° TCH 50'. Road.

RWY 35: REIL. PAPI(P2L)—GA 3.0° TCH 50'. Rgt tfc.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 17-35, PAPI Rwy 17 and Rwy 35, REIL Rwy 17 and Rwy 35—CTAF.

AIRPORT REMARKS: Attended Sun-Fri 1600-0100Z±. Migratory flocks of waterfowl invof arpt during spring and fall. Wildlife invof arpt. Farming activities and equipment using rws and twys. Sensitive AG crops adjacent to rwy/twy. Rotocraft should avoid operating in these areas. Be alert for glider ops May-Sept. US Forest Svc fire ops May-Sept. Ldg fee.

AIRPORT MANAGER: (530) 842-8259

WEATHER DATA SOURCES: ASOS 121.125 (530) 459-0267.

COMMUNICATIONS: CTAF/UNICOM 123.0

ANTELOPE MOUNTAIN RCO 122.4 (RANCHO MURIETA RADIO)

Ⓡ **SEATTLE CENTER APP/DEP CON** 124.85

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.

FORT JONES (L) VOR/DME 109.6 FJS Chan 33 N41°26.98'

W122°48.39' 018° 25.1 NM to fld. 4900/19E. **HIWAS.**

VOR unusable:

080°-135° byd 19 NM

080°-135° byd 9 NM blo 13,000'

190°-300° byd 19 NM

200°-300° byd 8 NM blo 14,000'

DME unusable:

190°-275° byd 19 NM blo 16,000'

MONTAGUE NDB (MHW) 404 MOG N41°43.64' W122°28.90' 356° 3.3 NM to fld. 2629/15E. NOTAM FILE SIY.

NDB unmonitored.

NDB unusable:

190°-200° byd 10 NM

