

DOUGLAS MUNI (DGL)(KDGL) 2 E UTC-7 N31°20.56' W109°30.39'

4173 B LRA NOTAM FILE PRC

PHOENIX
H-4K, L-5D

RWY 03-21: H5760X75 (ASPH) MIRL

RWY 03: PAPI(P4L)—GA 4.0° TCH 40'. Brush. Rgt tfc.

RWY 21: PAPI(P4L)—GA 4.0° TCH 50'. Brush.

RWY 18-36: 4095X100 (DIRT)

RWY 18: Brush.

RWY 36: Brush. Rgt tfc.

SERVICE: FUEL 100LL, JET A LGT PAPI Rwy 21 OTS indef. Rwy 03 PAPI OTS indef. Rwy 21 PAPI OTS indef.

AIRPORT REMARKS: Attended Mon-Fri 1400-0100Z, 24 hr 100LL avbl with major credit card. For svc after hours call 520-368-6015. Rwy 03-21 has 1" - 6" cracks across rwy. Rwy 18-36 has +4' brush, rocks and uneven surface for 3/4 of rwy length. Rwy 18-36 CLOSED indef. Rwy 21 50' twr 1350' from thld 550' left lgtd. Mountains 1 1/2 miles east. Rwy 18-36 brush on both sides 70 ft from centerline full length of rwy. Rwy 18-36 surface rough and rutted. Rwy 18-36 +3 ft bump 300 ft from Rwy 18 thld. Rwy 18-36, 2 ft bump crossing twy to Rwy 03-21. Personnel on ATVS near acft opr areas-unrstd. Flight notification svc avbl. Exts contrr act in cntr of airfield assoc with the bdr wall const. Const eqpt and mobile bldgs lctd on cntr fld acft ramp and on ptn of Rwy 18-36 (indefly clsd) S of cntr twy.

AIRPORT MANAGER: (520) 368-6015

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.6 (PRESCOTT RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE DUG.

(VL) (H) VORTACW 108.8 DUG Chan 25 N31°28.36' W109°36.12' 135° 9.2 NM to fld. 4131/13E.

TACAN AZIMUTH unusable:

045°-065° byd 26 NM blo 10,000'

065°-095° byd 28 NM blo 9,500'

355°-010° byd 35 NM blo 11,300'

DME unusable:

045°-065° byd 26 NM blo 10,000'

065°-095° byd 28 NM blo 9,500'

355°-010° byd 35 NM blo 11,300'

VOR unusable:

046°-063° byd 40 NM blo 11,000'

046°-063° byd 49 NM blo 16,000'

046°-063° byd 63 NM

253°-263° byd 40 NM blo 16,000'

253°-263° byd 66 NM

264°-277° byd 40 NM

278°-288° byd 40 NM blo 16,000'

278°-288° byd 52 NM

305°-316° byd 40 NM

345°-045° byd 40 NM

