

SELLS (E78) 2 NW UTC-7 N31°55.96' W111°53.66'

2409 NOTAM FILE PRC

RWY 04-22: H5830X60 (ASPH) S-12.5

RWY 04: Trees.

RWY 22: Trees.

AIRPORT REMARKS: Unattended. Livestock on and in/ov arpt. U.S. border patrol has 1500 gallon Jet A tanker truck parked 16 ft from the pavement edge near mid-point of rwy. Rwy 04-22 +3' wide cracks (longitudinal and transverse) full length of rwy. Isolated holes less than 1-2 sq ft in rwy. Rwy 04-22 large unfilled cracks, loose aggregated on surface, isolated holes on rwy surface. Rwy 04-22 width 60 ft in some areas narrower due to bushes growing thru pavement. Rwy 04-22 15 to 18 ft trees and brush in primary sfc entire length of rwy, both sides. Rwy 04-22 8-15 inch drop-offs at edges of rwy. 3 ft ditches along/within 3 ft of rwy edges. Rwy 04-22 marked with 6 inch yellow centerline stripe only; markings faded; no rwy numbers. 5 tiedowns in primary sfc.

AIRPORT MANAGER: (520) 383-5546

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE TUS.

TUCSON (H) (H) VORTACW 116.0 TUS Chan 107 N32°05.71' W110°54.89' 247° 50.9 NM to fld. 2671/12E.

VOR unusable:

050°-080° byd 30 NM blo 11,500'

350°-020° byd 30 NM blo 13,000'

TACAN AZIMUTH unusable:

050°-080° byd 30 NM blo 11,500'

155°-165° byd 35 NM blo 13,000'


350°-020° byd 30 NM blo 13,000'

DME unusable:

050°-080° byd 30 NM blo 11,500'

155°-165° byd 35 NM blo 13,000'

350°-020° byd 30 NM blo 13,000'



SHOW LOW RGNL (SOW)(KSOW) 2 E UTC-7 N34°15.93' W110°00.34'

6416 B TPA-7216(800) Class III, ARFF Index A NOTAM FILE SOW

RWY 07-25: H7202X100 (ASPH) S-35, D-60 PCN 7 F/D/X/T MIRL

RWY 07: REIL. PAPI(P2L)—GA 3.0° TCH 32'. Thld dspcd 700'.

RWY 25: REIL. PAPI(P2L)—GA 3.0° TCH 49'. Rgt tfc.

RWY 04-22: H3938X60 (ASPH) S-12.5 PCN 7 F/D/Y/T

RWY 04: Rgt tfc.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-3938 TODA-3938 ASDA-3938 LDA-3938

RWY 07: TORA-7200 TODA-7200 ASDA-7200 LDA-6500

RWY 22: TORA-3938 TODA-3938 ASDA-3938 LDA-3938

RWY 25: TORA-7200 TODA-7200 ASDA-7200 LDA-7200

SERVICE: S2 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 07 and Rwy 25, PAPI Rwy 07 and Rwy 25, MIRL Rwy 07-25—CTAF.

AIRPORT REMARKS: Attended 1400-0200Z. Self-service fuel avbl continuously. Military tfc in/ov arpt. Simultaneous ops Rwy 22 and Rwy 25 prohibited. Rwy 04-22 not avbl for scheduled acr opns with more than 9 psgr seats or unscheduled acr at least 31 psgr seats. Rwy 04-22 and Rwy 07-25 not connected by pavement at AER 22. Overnight transient fees and commercial opr ldg fees applicable.

AIRPORT MANAGER: 928-532-4190

WEATHER DATA SOURCES: AWOS-3 118.075 (928) 532-0379.

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE SJN.

ST JOHNS (VH) (H) VORTAC 112.3 SJN Chan 70 N34°25.44' W109°08.61' 246° 43.9 NM to fld. 6840/12E.

VOR unusable:

097°-108° byd 40 NM

109°-119° byd 40 NM blo 18,000'

120°-222° byd 40 NM

PHOENIX

H-4K, L-5C, 8G

IAP

