

**SUPERIOR MUNI** (E81) 2 SW UTC-7 N33°16.67' W111°07.62'

PHOENIX

2646 NOTAM FILE PRC Not insp.

**RWY 04-22:** 3250X75 (GRVL)**RWY 22:** Tree.

**AIRPORT REMARKS:** Unattended. Emerg phone 520-689-5254 (police). Gate code 2646. Arpt manager recommends Idg uphill to the northeast. Rwy 04-22 east 2000 ft of rwy, excellent cond, west 1000 ft, good to fair. Rwy 04-22 brush and trees to a height of 12 ft, 75 ft from centerline on both sides. Mountain 4375' MSL located 9000' west of Rwy 04. Livestock on arpt. Rwy 04 thld marked by painted rubber tires, Rwy 22 thld unmarked. Obstructions brush NE rwy; terrain NE; hills and mtn SSW thru SW of arpt.

**AIRPORT MANAGER:** 520-689-5752**COMMUNICATIONS:** CTAF/UNICOM 122.95**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.**TAYLOR** (TYL)(KTYL) 2 SW UTC-7 N34°27.16' W110°06.90'

PHOENIX

5823 B NOTAM FILE PRC

H-4K, L-8G

**RWY 03-21:** H7001X75 (ASPH) MIRL 1.5% up SW

IAP


**RWY 03:** REIL. PAPI(P2L)—GA 4.0° TCH 49'.**RWY 21:** REIL. PAPI(P2L)—GA 3.0° TCH 43'.

**SERVICE:** S4 **FUEL** 100LL **LGT** ACTVT REIL Rwy 03 and Rwy 21; PAPI Rwy 03 and Rwy 21; MIRL Rwy 03-21—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1430-0000Z. Self service fuel available 24 hrs with major credit card. Wildlife on or invof arpt. For FBO ctc 928-606-9779. +4 - 9' trees and brush in primary surface NW side of rwy 100'-250' from centerline. Several rwy hold and exit signs out of svc indef.

**AIRPORT MANAGER:** 928-606-9779**WEATHER DATA SOURCES:** AWOS-3PT 119.075 (928) 387-2084.**COMMUNICATIONS:** CTAF/UNICOM 122.7① **ALBUQUERQUE CENTER APP/DEP CON** 132.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SJN.**ST JOHNS (H) (H) VORTAC** 112.3 SJN Chan 70 N34°25.44'

W109°08.61' 260° 48.2 NM to fld. 6840/12E.

**TEMPLE BAR** (U30) 1 SW UTC-7 N36°01.23' W114°20.10'

LAS VEGAS

1549 NOTAM FILE PRC

L-7E

**RWY 18-36:** H3500X50 (ASPH) S-10**RWY 18:** Rgt tfc.**RWY 36:** Brush.

**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Be alert for loose rock on north turn-a-round and on rwy. Be alert for vehicular traffic on rwy. Rwy 18-36 20' berm 180' west along full length of rwy. Rwy 18-36 numerous cracks on rwy with loose rock on surface. Ldg is recommended uphill to the south. Due to +2% up slope from Rwy 18 to Rwy 36. Do not use tie down area as parallel twy, back taxi on rwy. Actf ramp in failed condition wth ruts due to erosion, use south half of ramp area.

**AIRPORT MANAGER:** (702) 293-2011**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Los Angeles ARTCC at 661-575-2079.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RNO.**BOULDER CITY (H) (H) VORTACW** 116.7 BLD Chan 114 N35°59.75'

W114°51.81' 072° 25.8 NM to fld. 3642/15E.

Unusable:

155°-180° byd 30 NM blo 9,000'

**COMM/NAV/WEATHER REMARKS:** Call 122.8 for transportation.